

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-10826

Indicate Type of Lease
STATE ☒ FEE ☐

State Oil & Gas Lease No.
B-514

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
Mack Energy Corporation

Address of Operator
P.O. Box 960 Artesia, NM 88211-0960

Well Location

Unit Letter F : 1700 Feet From The north Line and 2050 Feet From The west Line

Section 28 Township 17S Range 29E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)

3550GR

Lease Name or Unit Agreement Name
G-J West Coop Unit

Well No.

14

Pool name or Wildcat

Grbg Jackson SR Q Grbg SA

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify OCD 24 hrs. Before starting

1. POH w/ rods & tubing

2. RIH open end to 2600 spot 100' plug from 2500 to 2600 woc & tag Min. cmt Plug 255x.

3. Spot 100' plug from 975 to 1075' (salt 1025) Perforate 4 1/2" csg @ 1075'. Squeeze 100' cmt Plug. Inside + Outside 4 1/2" csg. TAG

4. Spot 100' plug from 310 to 410 (8 5/8 shoe 367') Perforate 4 1/2" csg @ 410. Squeeze 100' cmt Plug. Inside + Outside 4 1/2" csg. TAG

5. Spot 30' plug from 30' to surface Perforate 4 1/2" csg @ 60'. Circulate cmt to surface. Inside + Outside 4 1/2" csg.

6. Cut off well head install dry hole marker

* Brine gel between cement Plugs.

Notify N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Wayne Brooks

TITLE Agent

DATE 03-23-01

TYPE OR PRINT NAME Wayne Brooks

TELEPHONE NO. (915)580-7161

(This space for State Use)

APPROVED BY

Mel S. Walker

TITLE Field Rep. II

DATE 3/23/2001

CONDITIONS OF APPROVAL, IF ANY: