JUL 3 11 1993

G-J West Coop Unit #108 Continued Form C-103 1/27/93



12/15/92	Ran in hole w/globe basket and clean out iron. Ran
	in hole w/bit and clean out hole.
12/16/92	Clean out to 5050'. Circ to log. Pipe stuck. Ran
	freepoint stuck at 4300'.
12/17/92	Circ hole w/brine wtr and starch. Pipe came free
	POOH
12/18/92	Ran in hole w/pipe and circ hole and log well.
12/19/92	Ran in hole w/halliburton floatshoe and floatcollar
	and 14 Centrilizers on every 3rd jt. Ran 112 jts.
	5 1/2" 17# csg. Landed csg at 5050'. Cemented csg
	w/1000sx Class C, with 6# salt, 3/10 of 1% CF-14 and
	500 gals WMW-1 (mud flush).
12/20/92	Ran Cmt Temp. Survey. TOC 2900'.
12/23/92	Rigged up HLS. Ran CBL and perfed csg from 4980-90'.
12/28/92	Acidized perfs 4980-90' w/500 gals 15% NE acid. Swab
	test all wtr.
12/29/92	1400' entry no oil.
12/30/92	Perfed csg @ 3123-3325'.
12/31/92	Acidized perfs 3123-3325' w/1000 gals acid.
01/03/93	Frac perfs w/60,000 gals gelled wtr and 500sx 20/40
	and 700sx 12/20 sand.
01/04/93	Put well on pump.

Pumping 12 BOPD w/120 BWPD