

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other Instructions on  
reverse side)

Oil Cons.  
J.M. Div-Dist. 2  
Budget Bureau No. 1004-0135  
1301 W. Grand Avenue  
Expires August 31, 2005  
Artesia NM 88210

457

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC-029418-B	
2. NAME OF OPERATOR The Wiser Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		7. LEASE NAME Lea "C"	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  660' FSL & 660' FWL Unit M		8. WELL NO. 12	
		9. API WELL NO. 30-015-20697	
		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers QN GB SA	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11-T17S-R31E	
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3934' DF	12. COUNTY OR PARISH Eddy County	13. STATE NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT * <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Add Seven Rivers zone</u> (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
(Other)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5/14/01 MIRU Key Well Service. POH w/rods & pump. ND WH. RU BOP. POH w/2-3/8" tbg. LD BHA. RU Computalog WL & perforated Seven Rives f/2311',15',16',21',25',26',29',30',45',57',58',65',70',2419',58',59',60',77',78' & 98' w/2 SPF. (40 holes) RD WL.

5/15/01 RIH w/2-3/8" x 5-1/2" RBP & pkr. to 2540'. Set RBP. RU Hughes. Set pkr. @ 2535'. Tested RBP & tbg. to 3500#. Unset pkr. & spot 200 gals. 15% NE-FE acid across perf. intervals. POH to 2260'. Set pkr. Acidized Seven Rivers 2311'-2498' w/2800 gals. 15% NE-FE acid w/80 ball sealers. Best block 1200#. Best break 1100#. Balled out @ 3500# w/60 balls on & 2700 gals. of acid away. Flushed w/13 bbls. fresh water. Formation broke @ 1900#. ATP 2400# @ 3.3 bpm. MTP 3500# @ 3.5 bpm. ISIP 1600#. 5 min. 1470#. 10 min. 1450#. 15 min. 1430#. RD Hughes. 1 hr. SI 1250#.

5/16/01 RU swab. Tagged fluid @ 1200'. RIH w/2-3/8" tbg. Picked up RBP. POH w/2-3/8" tbg. LD RBP & pkr. RIH w/2-3/8" tbg. Tbg. @ 3816'. SN @ 3780'. RD BOP. NU WH. RIH w/rods & 1-1/2" x 16' pump. Left well pumping to Lea "C" Battery. RDMO.

ACCEPTED FOR RECORD

OCT 24 2001

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Production Tech II ALEXIS C. SWOBODA DATE August 5, 2001  
PETROLEUM ENGINEER

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instruction On Reverse Side