

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

AMENDED

WELL API NO. 30-015-22092
5. Indicate Type of Lease FEDERAL <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LC-208793A
7. Lease Name or Unit Agreement Name BURCH KEELY UNIT
8. Well No. 94
9. Pool name or Wildcat GRBG JACKSON SR Q GRBG SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW	
2. Name of Operator MARBOB ENERGY CORPORATION	
3. Address of Operator P. O. BOX 227, ARTESIA, NM 88210	
4. Well Location Unit Letter <u>K</u> : <u>1650</u> Feet From The <u>S</u> Line and <u>2310</u> Feet From The <u>W</u> Line Section <u>19</u> Township <u>17S</u> Range <u>30E</u> NMPM <u>EDDY</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MARBOB ENERGY PROPOSES TO SET CIBP @ 2900', SET  
EAZY DRILL @ 2825', SQZ PERFS @ 2839-2847', SET  
EAZY DRILL @ 2475', SQZ PERFS @ 2490-2597', SET  
EAZY DRILL @ 1575', SQZ PERFS @ 1601-1607', DRILL  
OUT EACH PLUG & TST, RE-SQZ IF NEEDED, RUN PRODUCTION  
PKR & SET @ 2900', CIRC PKR FLUID, RUN CHART TEST,  
PUT ON INJECTION.

RECEIVED  
OCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rhonda Nelson TITLE Production Clerk DATE 4/9/98

TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. 748-3303

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: Record Only