9-30-8t: Drlg.

9-25 thru

:78-77 '87-6

"C" neat. Circ 217 sx. Bumped plug w/2000 psi. ND BOP, set slips.

NU BOP, tst'd BOP & tst'd csg to 1500 psi for 15 min. Drld cmt &

9-22-84: (Cont) 1/4#/sx flocele, 3#/sx gilsonite, 8#/sx salt followed by 300 sx