

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

15F

5. LEASE DESIGNATION AND SERIAL NO.

LC-062052

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER
MAR 7 11 07 AM '89

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
William A. & Edward R. Hudson ✓
CAR ARELL

8. FARM OR LEASE NAME

Shugart "B"

3. ADDRESS OF OPERATOR
Box 9, Maljamar, New Mexico 88264

9. WELL NO.

3

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

Shugart-Queen-G

660' from north and 1980' from east lines of
Sec. 15-18S-31E

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15-18S-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)
3705'
O. C. D.
CARLSBAD OFFICE

12. COUNTY OR PARISH

13. STATE
Eddy N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF PULL OR ALTER CASING
FRACTURE TREAT MULTIPLE COMPLETE
SHOOT OR ACIDIZE ABANDON*
REPAIR WELL CHANGE PLANS
(Other)

WATER SHUT-OFF REPAIRING WELL
FRACTURE TREATMENT ALTERING CASING
SHOOTING OR ACIDIZING ABANDONMENT*
(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On March 2, 1989, this well was plugged and abandoned using the following procedure:

Set a "cast iron" bridge plug at 3226', placed 35' cement on top of plug, filled hole with salt gel mud to 1980', placed 100' cement from 1980' to 1880', filled hole with salt gel mud to 700', perforated 5-1/2" casing at 860' with 3 holes, pumped 180 sks. class "C" cement into perforations at 860' w/ 300 psi. pressure, displaced cement with fresh water, left cement plug, covering 8-5/8" casing shoe from 860' to 663'. This plug was tagged at 663', placed 60' cement at surface, installed 4" x 8" marker with well data.

This plugging procedure was witnessed and approved by BLM representative, Mr. Dale Carpenter from Carlsbad.

Post ID-2
3-17-89
P4A

18. I hereby certify that the foregoing is true and correct

SIGNED *Dale Carpenter*

TITLE Prod. Supt.

DATE 3/3/89

(This space for Federal or State office use)

ORIG. SCD. RAJ GRI

APPROVED BY *Raj GRI*

TITLE

DATE 3-9-89

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well burd.
Liability on the well is retained until
surface restoration is completed.

*See Instructions on Reverse Side