



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. LC 050797  
Unit \_\_\_\_\_

ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

OCT 16 1962

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

C O P Y

*Wells (copy)*

May 21, 19 62

Well No. 10 is located 2322 ft. from ~~N~~<sub>S</sub> line and 1.005 ft. from ~~E~~<sub>W</sub> line of sec. 13

SW $\frac{1}{4}$  Sec. 13 20 S. 28 E N.M.P.M.  
( $\frac{1}{4}$  Sec. and Sec. No.) (Twp.) (Range) (Meridian)

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 3249 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2" tubing in packer was set @ 709 & 100 sax of cement was squeezed in Russell sand by Dow. Hole was then filled to surface with mud (no salvage of 7" csg. was attempted) and a 5 sax plug set in 7" csg. at surface as a marker. Grounds are clean.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Neil H. Wills

Address Box 529

Carlsbad, N.M.

By orig. /s/ Neil H. Wills

Title Owner