

### SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A		5. LEASE DESIGNATION AND SERIAL NO. NM 9531
2. NAME OF OPERATOR Yates Petroleum Corporation ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.) At surface 1650' FNL & 630' FEL, Sec. 14-T21S-R2E		8. FARM OR LEASE NAME Hilliard BF Federal
14. PERMIT NO. 30-015-20059		9. WELL NO. 1-Y
15. ELEVATIONS (Show whether D, RT, GR, KB) 4139' GR; 4154' KB		10. FIELD AND POOL, OR WILDCAT West Indian Basin Morrow
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit H, Sec. 14-21S-22E
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		12. COUNTY OR PARISH Eddy
		13. STATE NM

RECEIVED BY  
JUN 02 1986  
O. C. D.  
ARTESIA, OFFICE

#### NOTICE OF INTENTION TO:

#### SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

This well is not commercial in Strawn completion at 7927-41 and 8238-88'. We propose to plug and abandon well as follows:

- 1) Set CIBP at 7675' w/35' cement cap or spot a 70 sx Class C cement plug @8340-7650' across Strawn perfs to top of Strawn and tag plug.
- 2) Spot 20 sx Class C cement plug @6650-6500' across top of Penn.
- 3) Spot 15 sx Class C cement plug @5120-5000' across top of Wolfcamp.
- 4) Cut and pull 5½" casing at about 3300' and spot 35 sx plug 50' in and out of stub and tag.
- 5) Spot 35 sx plug across 9-5/8" shoe @1175-1075' - Tag plug.
- 6) Spot 30 sx plug at 380-280' (13-3/8" shoe).
- 7) Spot a 50' plug (15 sx) at surface.

Will install regulation abandonment marker and clean location, prep for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Aranta D. D. D.</u>	TITLE <u>Production Supervisor</u>	DATE <u>5-22-86</u>
(This space for Federal or State office use)		
APPROVED BY <u>Aranta D. D. D.</u>	TITLE <u></u>	DATE <u>5-24-86</u>
CONDITIONS OF APPROVAL, IF ANY:		

\*See Instructions on Reverse Side

