

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Department of Energy, Minerals and Natural Resources

Form C-103
Revised 1-1-89

clerk
of

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240
DISTRICT II
P. O. Drawer DD, Artesia, NM 88210-2834
DISTRICT III
000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 S. Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-20494
5. Indicate Type of Lease Fee
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Catclaw Draw Unit
8. Well No. 2
9. Pool name or Wildcat Catclaw Draw Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Hallwood Petroleum, Inc.	3. Address of Operator P. O. Box 378111, Denver, CO 80237
4. Well Location Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line Section 23 Township 21S Range 25E NMPM NE/4 Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3305' GL 3317' KB		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

Hallwood plugged and abandoned this well during November 29, 1999 thru December 2, 1999.

Rig up Baker Atlas wireline. Set 4 1/2" CIBP @ 9152' and capped w/ 35' cmt. Set 2nd CIBP @ 8725' and capped w/ 35' cmt. Cut casing @ 2100' and pulled free. Rigged up Bull Rogers casing crew and pulled 63 jts of 4 1/2", 11.6#, K-55 csg. Rigged up Howco, circ well w/ plug mud. Pump 150 sx Premium Plus cmt w/2% CaCl, displace w/ plug mud. Tag TOC @ 1619', pump 75 sx of Premium Plus cement @ 510', pump 30 sx Premium Plus cmt @ 100, top off casing w/ cmt. Install dry hole marker. OCD officer J. Guy witness plugging.

Well is plugged and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Nonya K. Durham*

TITLE

Production Reporting
Supervisor

DATE **01/06/00**

TYPE OR PRINT NAME **Nonya K. Durham**

TELEPHONE NO. **(303) 850-6257**

(This space for State Use)

APPROVED BY *[Signature]*

TITLE

DATE

10-24-01

CONDITIONS OF APPROVAL, IF ANY: