

(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN ORIGINAL
(Other instructions
verse side)

copy to SF
BUDGET APPROVED
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NY 0295006
2. NAME OF OPERATOR CRIST DRILLING COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. BOX 1699 MIDLAND TX 79702		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) UNIT N, 670' TOL, 1902' FWL		8. FARM OR LEASE NAME REESE CLEVELAND-FEDERAL
14. PERMIT NO.		9. WELL NO. 1-Y
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4357' GR, 4373' RKS		10. FIELD AND POOL, OR WILDCAT ROCKY ARROYO
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SECTION 33 T-21-S, R-22-S
		12. COUNTY OR PARISH EDDY
		13. STATE NEW MEXICO

RECEIVED

MAR 31 1977

O. C. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTE: USGS Representative Mr. James Brasfield witnessed all plugs.

1-4-77 Moved in csg. pullers.

1-5,6-77 Tried to release pkr @ 9100' w/out success. Backed off tbq w/seal divider. Pulled 206 jts N-80 tbq. Ran 5 1/2" csg gauge ring to 8700'.

1-7-77 Set CRSP @ 8700' & dumped 4 sx cement on top of BP w/dump bailer. Welded on lift nipple. Stretched pipe & pulled slips. RU csg jacks & re-stretched pipe. Shot pipe @ 9214'-would not come free. Re-shot pipe @ 4980'-worked pipe free. Commenced pulling csg.

1-8-77 Finished pulling csg. Rec. 152 jts (5010') 5 1/2" csg.

1-11-77 Ran 2-3/8" OD, tbq, to 5029'. Loaded hole & mixed 20 sx salt water gel. Spotted cement plugs as follows: 25 sx @ 5029', 30 sx @ 2973', 30 sx @ 2309' & 35 sx @ 1961'.

1-12-77 Cut off head. Set 10 sx plug at surface w/dry hole marker.

WELL ABANDONED 1-12-77

Notification will be given when location is ready for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **General Superintendent**

DATE **1-12-77**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side