

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION
RECEIVED

MAR 29 1973

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS **D. C. C.**
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PRESENT WELL. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>dry hole</u>		7. Unit Agreement Name
2. Name of Operator <u>David Easken</u>		8. Farm or Lease Name <u>Avalon State</u>
3. Address of Operator <u>603 First National Bank Bldg., Midland, Texas 79701</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>T</u> , <u>1550</u> FEET FROM THE <u>West</u> LINE AND <u>1440</u> FEET FROM THE <u>South</u> LINE, SECTION <u>7</u> TOWNSHIP <u>21-S</u> RANGE <u>26-T</u> NMPM.		10. Field and Pool, or Wildcat <u>Undesignated 'orrow</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3305 GL, 3321 KB</u>		12. County <u>Elly</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. "D. 10,800'.
2. Spot cement plugs: 10,625'-10,725' w/ 42 sxs., 10,300'-10,400' w/42 sxs., 9,000' -9,900' w/42 sxs., 8,200' - 8,100' w/42 sxs., 3,900' - 4,000' w/42 sxs., 2,100' - 2,200' w/84 sxs., and 11 sxs. at surface.
3. Cut off casing.
4. Fill cellar.
5. Level location and pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James P. Henry TITLE Agent DATE Mar. 23, 1973

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: