	UPTED STATES RTML OF THE INTERI	-	BA Ex	orm approved. udget Bureau No. xpires August 31. BE DESIGNATION AND	1985	
SUNDRY NO	OTICES AND REPORTS (opposals to drill or to deepen or plug b LICATION FOR PERMIT—" for such pr	ON WELLS	6. IF IR	NM-12828 MDIam, ALLOTTER OR	TRIBE NAME	
OIL GAS X OTHE			7. UMIT	AGREMENT HAME		
NAME OF OPERATOR		FEB 01 '88	8. PARM	OR LEASE HAME		
Union Texas Petroleum Corp. 🗸			She1	Shelby Federal		
P O Roy 2120 Pouge	on, Texas 77252-2120	O. C. D.	9. WHLE	L BO.		
LOCATION OF WELL (Report location See also space 17 below.)	on clearly and in accordance with any	ARTESIA, OFFICE		LD AND POOL, OR WIL	LDCAT	
At surface				ittrick Hill		
1900' FSL & 2200' FW	π		11. smc.	., T., B., M., OR BLE URVBY OR ARBA	LIFD	
PERMIT NO.	15. BLEVATIONS (Show whether DF,	BT. GR. etc.)	12. coo	12, T22S,	R24E	
	3859 GL		Ed	ldy	NM_	
Check .	Appropriate Box To Indicate N	ature of Notice, Report, or t	Other Da	rta		
NOTICE OF IN		•	סיום דאום פ			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER BHCT-OFF		REPAIRING WELL		
PRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE X	PRACTURE TREATMENT		ALTERING CASING		
REPAIR WELL	CHANGE PLANS	8BOOTING OR ACIDIZING (Other)		ABANDON MENT*		
REPAIR WALL						
(Other)	OPERATIONS (Cleusly state all pertinent ctionally drilled, give subsurface locati	(NOTE Report result completion or Recomp details, and give pertinent dates ons and measured and true vertice	pletion Repo	ort and Log form		
Abandonment Procedu 1. Cut off tbg. @ 2. Run CBL to dete 3. Cut 4-1/2 above 4. Pull 4-1/2 & se	<u>re</u> : 805', set retainer in 4 rmine top of cement in	details, and give pertinent dates one and measured and true vertice. -1/2 above 805'. 4-1/2" csg.	pletion Repo	ort and Log form	Starting any sones perti-	
Abandonment Procedu 1. Cut off tbg. @ 2. Run CBL to dete 3. Cut 4-1/2 above 4. Pull 4-1/2 & se	re: 805', set retainer in 4 rmine top of cement in top of cement. t retainer in 8-5/8" cs	details, and give pertinent dates one and measured and true vertice. -1/2 above 805'. 4-1/2" csg.	pletion Repo	estimated date of for all markers and	RECEIVED	
Abandonment Procedu 1. Cut off tbg. @ 2. Run CBL to dete 3. Cut 4-1/2 above 4. Pull 4-1/2 & se 5. Pmp prescribed a I hereby certif that the foregoing BIGNED	re: 805', set retainer in 4 rmine top of cement in top of cement. t retainer in 8-5/8" cs amount cmt., cut off an	details, and give pertinent dates one and measured and true vertice. -1/2 above 805'. 4-1/2" csg.	, including all depths f	estimated date of for all markers and	RIGGE VED	
Abandonment Procedu 1. Cut off tbg. @ 2. Run CBL to dete 3. Cut 4-1/2 above 4. Pull 4-1/2 & se 5. Pmp prescribed a	re: 805', set retainer in 4 rmine top of cement in top of cement. t retainer in 8-5/8" cs amount cmt., cut off an	details, and give pertinent dates one and true vertice. -1/2 above 805'. 4-1/2" csg. g. d abandon.	DA	estimated date of for all markers and	RECEIVED	

surface of the See Instructions on Reverse Side