

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

JUL 10 1975

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (MFCAM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
1. Name of Operator Cities Service Oil Company ✓		5. State Oil & Gas Lease No. L-713
2. Address of Operator Box 1919 - Midland, Texas 79701		7. Unit Agreement Name
3. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>21S</u> RANGE <u>27E</u> NMPL		8. Field or Lease Name State Oil Com.
4. Elevation (Shade whether DE, RT, GR, etc.) 3255' GR		9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Bone Springs		11. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 11,685' Shale FBTD 9160' Lime. This well was plugged and abandoned in the following manner:

1. MIRU pulling unit, unseated racker @ 6958' and pulled tubing.
2. Set a CIRP @ 6900' and dumped a 5 sack cement plug on top of CIRP @ 6900' - 6850'.
3. Shot 5-1/2" casing @ 5601' and pulled 143 Jts. (5618') 5-1/2" OD 17# N-80 casing.
4. Loaded hole with mud laden fluid.
5. Spotted a 35 sack cement plug 1/2 in and 1/2 out of 5-1/2" casing stub @ 5650' - 5550'.
6. Spotted a 40 sack cement plug @ 4970' - 4870' across top of Bone Springs.
7. Spotted a 40 sack cement plug 1/2 in and 1/2 out of 9-5/8" casing stub @ 3050' - 2950'.
8. Set a 10 sack cement surface plug @ 10' - 0' with a 4" dry hole marker extending 4' above the surface to designate a plugged and abandoned location.
9. Cleared location of all casing and debris.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Region Operation Manager DATE July 8, 1975

APPROVED BY [Signature] TITLE SUPERVISOR, DISTRICT II DATE JUL 15 1975

CONDITIONS OF APPROVAL, IF ANY: