

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

**RECEIVED BY**  
NEW MEXICO OIL CONSERVATION COMMISSION  
**JUL 11 1985**  
**O. C. D.**  
**ARTESIA, OFFICE**

**RECEIVED BY**  
NEW MEXICO OIL CONSERVATION COMMISSION  
**JUL 11 1985**  
**O. C. D.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**V-171**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> 2. Name of Operator: <b>TXO Production Corp.</b> 3. Address of Operator: <b>900 Wilco Bldg., Midland, TX 79701</b> 4. Location of Well UNIT LETTER <b>H</b> <b>2000</b> FEET FROM THE <b>NORTH</b> LINE AND <b>890</b> FEET FROM <b>EAST</b> THE <del>West</del> LINE, SECTION <b>18</b> TOWNSHIP <b>21-S</b> RANGE <b>26-E</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <del>3311 GR</del> <b>3272.8 GR</b>	7. Unit Agreement Name  8. Farm or Lease Name <b>Catclaw Draw St Com</b> 9. Well No. <b>2</b> 10. Field and Pool, or Wildcat <b>Catclaw St. 21</b> 12. County <b>Eddy</b>
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>
--	---	---	---

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOH w/tbg & UNI-6 pkr.  
 TIH w/GR & junk basket to 10470'.  
 Free pt 4 1/2" csg (app. 7850').  
 Set 4 1/2" CIBP @ 10,450'. Dump 35' cmt.  
 Set 35 sx cmt @ 9370' (in 4 1/2).  
 Set 10 sx cmt @ 8120 (in 4 1/2).  
 Cut & pull 4 1/2" @ 7800' (50' above free pt).  
 Set 35 sx cmt @ 7850' (on 4 1/2 stub).  
 Tag TOC (app. 50' in OH).  
 Set 35 sx cmt @ 5800' (in OH).  
 Set 35 sx cmt @ 4120' (in OH).  
 Set 35 sx cmt @ 2300' (at 8 5/8 shoe).  
 Tag TOC (app 50' in 8 5/8).  
 Set 35 sx cmt @ 550' (in 8 5/8).  
 Set 10 sx @ surface.

16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale D. Lovely TITLE Production Engineer DATE 6-27-85

**\* MIN. PLUG SIZE = 25 SXS.**

APPROVED BY \_\_\_\_\_ TITLE ORIGINAL SIGNED BY LARRY BROOKS DATE JUL 12 1985  
 GEOLOGIST - NMOCD

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness  
**PLUGGING**