

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>Yates</u>		Lease <u>Stonewall</u> <u>EP</u> <u>St.</u>		Well # <u>6</u>	
Location of Well	Unit <u>C</u>	Section <u>30</u>	Township <u>20</u>	Range <u>28</u>	County <u>EDDY</u>
Drilling Contractor	<u>LARUE 2</u>		Type of Equipment <u>ROTARY</u>		
* Witness <u>APPROVED CASING PROGRAM</u>					
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>17 1/2"</u>	<u>13 3/8"</u>	<u>48#</u>	<u>NEW</u>	<u>550'</u>	<u>CIRC</u>
* <u>12 1/4"</u>	<u>8 5/8"</u>	<u>24-28#</u>	<u>"</u>	<u>2500'</u>	<u>CIRC</u>
<u>7 7/8"</u>	<u>5 1/2"</u>	<u>17-20#</u>	<u>"</u>	<u>TD'</u>	<u>(650) TIEBK TO 8 5/8"</u>
Casing Data:					
Surface <u> </u> joints of <u> </u> inch <u> </u> # Grade <u> </u>					
<u> </u> (Approved) (Rejected)					
Inspected by <u> </u> date <u> </u>					
Cementing Program					
Size of hole <u>12 1/4"</u> Size of Casing <u>8 5/8"</u> Sacks cement required <u> </u>					
Type of Shoe used <u>guide</u> Float collar used <u>insert</u> Btm 3 jts welded <u>yes</u>					
TD of hole <u>2469'</u> Set <u>2469'</u> Feet of <u>8 5/8"</u> Inch <u>24</u> # Grade <u>J-55</u>					
New-used csg. @ <u>2469'</u> with <u>250 2%cc</u> sacks neat cement around shoe					
+ <u>800</u> sax <u>pacemaker</u> additives (<u>5# lysol</u> , <u>25% CFR²</u> , <u>22% AFS</u> , <u>2% cc</u>)					
Plug down @ <u>8:30</u> (AM) (PM) Date <u>11/4/84</u>					
Cement circulated <u>No</u> No. of Sacks <u> </u>					
Cemented by <u>Western Co.</u> Witnessed by <u>M.S.</u>					
Bond Log <u> </u> Survey ran @ <u> </u> (AM) (PM) Date <u>11-6-84</u> top cement @ <u>1578</u>					
Casing test @ <u> </u> (AM) (PM) Date <u> </u>					
Method Used <u> </u> Witnessed by <u> </u>					
Checked for shut off @ <u> </u> (AM) (PM) Date <u> </u>					
Method used <u> </u> Witnessed by <u> </u>					
Remarks: <u>Was pumping tail end cement. When cement bridged off, Operator will drill out from well bore + run cement bond log.</u>					
<u>lost returns @ 1540' + regained.</u>					

Ran Bond log Top Cement @ 1578

Ran 1" to 1536 cement 200 SXC 2% CC

Tag @ 824 Ran 100 SXC 2% CC

Tag @ 824 Ran 50 SXC 3% CC

Tag @ 824 Ran 100 SXC 3% CC

Tag @ 597 Ran 200 SXC 3% CC circulate cement