ubmit 3 Copies 5 Appropriate District Office	Energy, Minerals and Natural Reso	surces Department	<u> </u>	Revised 1-1-89
<u>VISTRICT I</u> '.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-015	-24769
STRICT II O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		7504-2088	5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas L	ease No.
	TICES AND REPORTS ON WELL	S		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or U	nit Agreement Name
I. Type of Well: Of WELL WELL X	d other	RECONVED	South Ava	lon YI Com
2 Name of Operator	<u>a</u>	Dan a 1	8. Well No.	
YATES PETROLEUM CORPO	DRATION	DCT 05. g	9. Pool name or Wi	l Idcat
3. Address of Operator	Artocia NM 88210	0. C. D:		alley Strawn
4. Well Location	eet - Artesia, NM 88210	ARTESIA, OFFICE		
	80 Feet From The South	Line and2100	Feet From	The West Line
		age 26E	NMPM Eddy	. County
Section 23	Township 21.S Rar 10. Elevation (Show whether L	DF, RKB, RT, GR, etc.)	ininini Baay	
	3140'	GR		
11. Check	k Appropriate Box to Indicate N	Vature of Notice, R	leport, or Other	Data
	NTENTION TO:	SUE	BSEQUENT R	EPORT OF:
		REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRILLIN		PLUG AND ABANDONMENT
PULL OR ALTER CASING			EMENT JOB	_
OTHER:	OTHER: Perforate & acidize			X
work) SEE RULE 1103. 9-23-94 - Moved in ar Dropped standing valv Unset packer at 9857' packer and RBP. TIH packer at 9912'. Tes 9-24-94 - Rigged up a rigged down slick lin OK. Get off on/off a Set RBP at 9870'. Te 1000 psi, OK. Nippla 9-27-94 - Bled well a Unset packer at 9760 and RBP. Changed ou 9885'. Tested RBP to	perations (Clearly state all periment details, and the rigged up pulling unit. The and tested tubing to 250 . Dropped down and unset with Uni VI packer with 1 sted annulus to 1000#, OK. slick line. TIH with stan- ne. Loaded tubing with 2% tool. TOOH with 2-7/8" tu ested RBP to 1000 psi, OK. ed down BOP. Nippled up t down. Loaded casing and t '. Dropped down and unset t RBP and packer. TIH with o 2000 psi, would not hold o 2000 psi for 10 minutes, is the and complete to the best of my knowledge and the stand	Nippled down t 20 psi, OK. Tes RBP at 10021'. .78" profile nip Swabbed. ding valve. Set KCL water. Tes bing. TIH with Set packer at ree. Swabbed. ubing. Nippled RBP at 9870'. h RBP, packer a . Unset RBP at OK. Set packe	tree and nipp sted annulus TOOH with 2- ople and on/o t standing va st standing v RBP, packer 9760'. Test down tree an TOOH with 2- nd 2-7/8" tub 9885'. Move <u>r at 9693'.</u> CONTIN	<pre>led up BOP. to 1000#, OK. -7/8" tubing, ff tool. Set lve. TOOH and alve to 500 psi, and 2-7/8" tubing. ed annulus to d installed BOP 7/8" tubing, packer ing. Set RBP at d up and set at</pre>
(This space for State Use)				OCT 1 2 1994
APPROVED BY	VISOR. DISTRICT II	TILE		DATE