1. OIL [3] CAB []	·		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	ER	ñ£G£ √úD	
	/		8. PARM OR LEASE NAME
Bridge Oil Company,	, L. P. >		Govt. D A/C 2
12377 Morit Drive	Sto 1600 D-11-	my 75051 APR 30 '90	9. WELL NO.
4. LOCATION OF WELL (Report local	Ste. 1600, Dallas,	TX /5251	14
See also space 17 below.) At surface	and the decondance wi	O. C.D.	10. FIELD AND POOL, OR WILDCAT
Unit Letter R, 2310)' FSL & 2170' FEL	ARTESIA CEREGE	Fenton-Delaware N.W. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whe	ether DF. RT. GR. etc.)	Sec. 1, T21S, R27E
	KB 3201	200, 200, 200,	12. COUNTY OR PARISH 13. STATE
16.	· · · · · · · · · · · · · · · · · · ·		Eddy NM
		cale Nature of Notice, Report, or C	Other Data
NOTICE OF	INTENTION TO:	BUBSEQ	UENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ALTERING CABING ABANDONMENT*
REPAIR WELL	CHANGE PLANS		y Abandonment X
(Other)	: <u>r</u>	(NOTE: Report results Completion or Recogni	of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETE: proposed work. If well is di nent to this work) *	D OPERATIONS (Clearly state all pe	ertinent details and glas nexts at 1	include the
Set CIBP @ 2660'.	Loaded hole with weigh the second	water with corrosion inhi	bitor. Pressure
Set CIBP @ 2660'. tested casing to	Loaded hole with weigh the second		bitor. Pressure
Set CIBP @ 2660'. tested casing to Casing Pressure T	Loaded hole with to 500#. Tested O.K. Pest Chart attached.	water with corrosion inhi	bitor. Pressure ily abandoned.
Set CIBP @ 2660'. tested casing to Casing Pressure T	Loaded hole with to 500#. Tested O.K. Pest Chart attached.	water with corrosion inhi	bitor. Pressure ily abandoned.
Set CIBP @ 2660'. tested casing to Casing Pressure T	Loaded hole with to 500#. Tested O.K. Pest Chart attached.	water with corrosion inhi	bitor. Pressure ily abandoned.
Set CIBP @ 2660'. tested casing to Casing Pressure T	Loaded hole with to 500#. Tested O.K. Pest Chart attached.	water with corrosion inhi	bitor. Pressure ily abandoned.
Set CIBP @ 2660'. tested casing to Casing Pressure T	Loaded hole with to 500#. Tested O.K. Pest Chart attached.	water with corrosion inhi Will leave well temporar	bitor. Pressure ily abandoned. ARCOARD COARD ARCOARD
Set CIBP @ 2660'. tested casing to Casing Pressure T	Loaded hole with to 500#. Tested O.K. Pest Chart attached.	water with corrosion inhi	bitor. Pressure ily abandoned.

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.