

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well ☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
OXY USA WTP Limited Partnership 192463

- | | |
|----------------------------------|-----------------------------------|
| 3a. Address | 3b. Phone No. (include area code) |
| P.O. Box 50250 Midland, TX 79710 | 915-685-5717 |

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1350 FNL 930 FEL SENE(H) Sec 23 TZIS RZZE

- | | |
|---|----------|
| 5. Lease Serial No. | NM 91500 |
| 6. If Indian, Allottee or Tribe Name | |
| 7. If Unit or CA/Agreement, Name and/or No. | |

8. Well Name and No.
Oxy Penny Loafer Federal #1

- 30-015-31453

10. Field and Pool, or Exploratory Area

- Indian Basin Morrow, W.

11. County or Parish, State
Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off	
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity	
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>SPUD, SET</u>	
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>CSG & CMT</u>	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See Other Side



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

David Stewart

Title

Regulatory Analyst

Signature

Date _____

215 lo

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title	
--------------	--

Date _____

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

20-15-31453

ATTACHMENT 3160-5
OXY USA INC.
OXY PENNY LOAFER FEDERAL #1
SEC 23 T21S R22E
EDDY COUNTY, NM

NOTIFIED BLM 10/20/00 OF SPUD. MIRU UTI #307, SPUD WELL @ 2300hrs MST 12/20/00. DRILL 17-1/2" HOLE TO 378' & LOST RETURNS, M&P LCM SWEEPS W/O SUCCESS, DRY DRILL TO TD @ 400', 12/21/00, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 400'. M&P 200sx CL H W/ 10% BWOC-10B + 10# GILSONITE + .25#/sx CELLOFLAKES + 1% CaCl₂ FOLLOWED BY 185sx 65:35 C/POZ W/ 6% BENTONITE + .25#/sx CELLOFLAKES + 2% CaCl₂ FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN 12/21/00, HAD INTERMITTENT CIRC DURING JOB, CIRC 36sx CMT TO PIT, WOC-6hrs. BLM NOTIFIED, GENE HUNT WITNESSED CMT JOB & TAG. RIH W/ 1", TAG CMT @ 25', TOP OUT W/ READY MIX. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 500#, OK. NU BOP & TEST BOP & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD 12/22/00.

DRILL 11" HOLE TO TD @ 2035' 12/26/00, RAN FLUID CALIPER, PUMP SWEEP. RIH W/ 8-5/8" 32# K55 CSG & SET @ 2035'. M&P 100sx CL H W/ 10% HNB + 10# GILSONITE + .25#/sx CELLOFLAKES + 1% CaCl₂ FOLLOWED BY M&P 405sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ + 5#/sx GILSONITE FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP /FW, PLUG DOWN 12/27/00, CIRC 199sx CMT TO PIT, WOC-4hrs. BLM NOTIFIED CATHY WITNESSED. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES, & CASING TO 2500#, BLM NOTIFIED OF BOP TEST, DID NOT WITNESS. TOTAL WOC-12hrs. RIH & TAG, DO CMT, TEST, DRILL AHEAD 12/28/00.

DRILL 7-7/8" HOLE TO TD @ 9370', 1/20/01, PUMP SWEEP & CHC. RIH W/ OPEN HOLE LOGS, POOH. RIH W/ 5-1/2" 17# P110 CSG & SET @ 9370'. M&P 1100sx 61/15/11-C/POZ/CSE W/ .5% FL-25 + .5% FL-52 + 8#/sx GILSONITE FOLLOWED BY 100sx CL C CMT W/ .7% FL-25, DISP W/ KCLW, PLUG DOWN 1/23/01. CEMENT DID NOT CIRCULATE, CALC TOC-4500'. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS, CUT OFF CSG, NUWH & JET CLEAN PITS, REL RIG @ 0300hrs MST 1/23/01. SI WOCU.