

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-0 15-21476
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Martin
8. Well No. 1
9. Pool name or Wildcat S. Carlsbad Strawn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator Dickson Petroleum, Inc.	
3. Address of Operator P. O. Box 50160	
4. Well Location Unit Letter F : 2198 Feet From The North Line and 1650 Feet From The West Line Section 20 Township 22S Range 27E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3136.5 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TOH w/tbg & pkr. TIH w/tbg. & spot 25 sack plug 9450 to 10340'. TAG
2. Pull tbg to 8992' & spot 50 sack plug 8992-8657'
3. Pull tbg to 6660' & spot 30 sack plug 6660-6466'
4. Pull tbg to 4600' & spot 30 sack plug 4660-4466'
5. Pull tbg to 1990' & spot 30 sack plug 1990-1856' TAG
6. Pull tbg to 1350' & spot 45 sack plug 1350-1228' TAG
7. Pull tbg to 410' & spot 55 sack plug 410-288' TAG
8. Pump 10 sacks at surface
9. Cut well head off, weld on plate & dry hole marker and clean location

* Brine gel between all cement plugs.

* Notify N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Arlen Dickson TITLE President DATE 10/05/98
TYPE OR PRINT NAME Arlen Dickson TELEPHONE NO. 915-686-9559

(This space for State Use)

APPROVED BY Michael S. [Signature] FIELD REP. II DATE Oct. 26-98