

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21526
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	APR 11 1997
2. Name of Operator Whiting Petroleum Corporation	3. Well No. 1
4. Address of Operator 1700 Broadway, Suite 2300, Denver, CO 80290	9. Pool name or Wildcat Carlsbad Wolfcamp, East
4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 1 Township 22S Range 27E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-20-97 Set CIBP @ 9145'

3-21-97 Circ hole w/mud, spotted 15 sks cmt from 9145'-8928'. Pull up to 7100' and spot 25 sks cmt 7100'-6739'.

3-24-97 Cut and pulled 5508' of 4-1/2" csg. Spotted 40 sks cmt @5656', tagged @5406'.

3-25-97 Spotted 30 sks cmt 3600'-3483', spotted 50 sks cmt @2645', tagged @2520'.
Spotted 30 sks cmt @529', tagged @413'.

3-26-97 Spotted 20 sks cmt 90'-surface. Cut off csg 4' below ground and installed dry hole marker. Removed anchors, cleaned and restored location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Douglas Sprague TITLE Division Oper. Engr. DATE 4-8-97
TYPE OR PRINT NAME Douglas Sprague TELEPHONE NO. (303) 837-1661

(This space for State Use)

APPROVED BY Mike S. Springfield TITLE Field Rep. II DATE 5-15-97
CONDITIONS OF APPROVAL, IF ANY: