

CISF

## N.M.O.C.D. COPY

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TWO COPIES  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

RECEIVED

5. LEASE DESIGNATION AND SERIAL NO.

NM-10895

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## APR 21 1986 DUNDY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. O. C. D.

OIL FIELD OFFICE ☒ OTHER

2. NAME OF OPERATOR

Hanagan Petroleum Corporation

3. ADDRESS OF OPERATOR

P.O. Box 1737, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

660' FNL and 1980' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Horseshoe Bend

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Undesignated Strawn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

22-23S-25E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3873 KB

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Change producing zone in strawn

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

T.D. 11,500', PBD 10,858' K.B., temporarily abandon producing strawn zone @ 9714-22 (perfs open on csg. side) pulled packer @ 9599', Went in hole w/on-off tool and tubing & latched on to Loc-Set Packer set @ 9862', pulled blanking plug, now producing through Strawn perfs. @ 10050-70; 10009-13; 9926-46.

CORRECTED COPY

18. I hereby certify that the foregoing is true and correct

SIGNED

*Hugh E. Hanagan*

TITLE

Vice President

DATE

4/17/80

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side