		. Y
Submit 3 Copies To Appropriate District	State of New Mexico	615 Form C-103
Office District I Energ	y, Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	•	WELL API NO. 30-015-22452
811 South First, Artesia, NM 88210 OIL	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Francis Dr. Santa Fe, NM 87503 3456	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND I	PEPOPTS OXEMELLS	7. Lease Name or Unit Agreement Name:
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEN OR PLUG BACKETO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 7. Lease Name or Unit Agreement Name: OCD 101 FOR SUCH Pardue Farms Gas Com		
PROPOSALS.)	PERMIT" (FORM C-101) POR SUCH	Pardue Farms Gas Com
1. Type of Well:	ARTESIA SO	
Oil Well Gas Well Oth 2. Name of Operator Ricks Exploration	er S	8. Well No.
L		#1
3. Address of Operator 210 Park Aven	ue, Suite 3000, OKC, OK 73102	9. Pool name or Wildcat South Culebra Bluff Atoka
4. Well Location		
Unit Letter G : 1980 f	eet from the North line and 19	80 c.c Fast .:
	eet from the North line and 19	
AMERICAN CO. C. S.	Township 23S Range 28E	NMPM Eddy County
10. Elev	ation (Show whether DR, RKB, RT, GR, e	tc.)
11. Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AN		
TEMPORARILY ABANDON	PLANS COMMENCE DR	
PULL OR ALTER CASING MULTIPLE COMPLET		ABANDONMENT D
OTHER:		orarily Abandon
12. Describe proposed or completed operati	ons. (Clearly state all pertinent details, an	ad give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompilation. 11/29/01 - Preparing for TA. MIRU W/O Rig. ND Tree, NU 7-1/16" 3K BOP w/7-1/16" 3Kx7-1/16" 10K Spool.		
Work pipe 2 hrs, unable to release Packer or On/Off Tool. SDON.		
11/30/01 - Work pipe 2 hrs, unable to work loose. MIRU W/L Truck. RIH & cut 2-3/8" tbg @11420'. POH. RD		
W/L Truck. TOH w/387 jts 2-3/8" 4.7# N80 EUE 8RD tbg. RU W/L Truck. RIH w/3.75" OD Gauge Ring & JB to 11420'. POH. Saw no restrictions. RIH & set 5" 18# CIBP @11370', capped w/35' cmt. POH. RD/Rei W/L		
Truck. TIH w/2-3/8" SSN & 380 jts 2-3/8" tbg. EOT @11196'. ND BOP, NU Tree. MIRU Kill Truck. Reverse		
CHC using 525 bbls 2% KCL wtr w/1 gal/10 bbls Packer fluid. Tested 7-5/8" csg & 5" liner to 500 psi w/no leak		
off. RD/Rel Kill Truck. SDON. 12/01/01		
RD/Rel W/O Rig & all rental equipmen	nt.	
01/31/02		500
Tested OK. Well TA.	Compliance Officer. Pressured up to Temporary Abandon Status	500 psi & held f/30 min. No bleed off.
	Approved Until	
I hereby certify that the information above is tru	-31-03	ge and belief.
Palsta		
SIGNATURE Mull flag	TITLE Engineer	DATE_ 2/25/02
Type or print name Paul Legg		Telephone No. (405) 516-1100
(This space for State use)	A _ 11	1 MAR 6 2002
APPPROVED BY	TITLE July	DATE V ZOUZ
	HILE WALL	