

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	<input checked="" type="checkbox"/>	
FILE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
U.S.G.S.		
LAND OFFICE		
OPERATOR	<input checked="" type="checkbox"/>	

RECEIVED BY
MAY 02 1986
O. C. D.
ARTESIA OFFICE

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State For

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER

2. Name of Operator
The Eastland Oil Company

3. Address of Operator
P. O. Drawer 3488, Midland, Texas 79702

4. Location of Well
UNIT LETTER M 990 FEET FROM THE South LINE AND 330 FEET FROM
THE West LINE, SECTION 32 TOWNSHIP 22S RANGE 28E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name
H. G. Faulk

9. Well No.
1

10. Field and Pool, or Wildcat
Terradura Bend (Delaware)

15. Elevation (Show whether DF, RT, GR, etc.)
3047' GR, 3048' DF

12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Using a pulling unit and Halliburton Services, work was begun on April 21, 1986 to plug and abandon H. G. Faulk #1 as follows:

1. Ran 2" tubing open-ended to 2500' and circulated hole with 9.5# mud.
2. Spotted plug with 25 sx class C cement and 2% CaCl₂ at 2500' in 4½" csg.
3. Waited 2 hours and tagged plug with tubing at 2250'.
4. Laid down tbg. to 1602' and set plug from 1602' to 1325' with 25 sx.
5. Laid down tbg. to 519' and set plug with 25 sx class C and 2% CaCl₂ in 4½" csg.
6. Waited 2 hours and tagged plug at 150' with tubing.
7. Set plug with 10 sx at surface.
8. Installed 4"X4' marker. Plugging complete 4-22-86.
9. The Artesia District Office will be notified as soon as location is ready for inspection.

Post ID 2
5-9-86
P+R

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED George D. Neal TITLE Vice President - Production DATE May 1, 1986
George D. Neal

D. DATE 2/5/87