

Submit 3 Copies to Appropriate District Office

T  
CIST  
Op

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088, Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

NOV 13 '89

WELL API NO. 30-015-22928
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-4764
7. Lease Name or Unit Agreement Name Oscar State
8. Well No. 1
9. Pool name or Wildcat Owen Mesa-Atoka Gas

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Oryx Energy Company
3. Address of Operator P. O. Box 1861, Midland, Texas 79702
4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 36 Township 24-S Range 29-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3101.6' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>Re-perf &amp; Stress Frac</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Re-perf &amp; Stress Frac</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- APOLLO WL RUN 1-11/16", 12GC, .32 EH STRIP GUN. PERF (ATOKA) 12,730-12,737 W/4 JSPF (32 TOTAL HOLES). POH.
- RIH W/1-1/4" X 12' STRESS FRAC TOOL ON WL. LOAD HOLE IF FLUID LEVEL BELOW 500' FS. STIMULATE 12,730-737. POH.
- FLOW BACK WELL FOR CLEAN-UP & TEST.

Continued-Page 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE Accountant DATE 10-17-89  
TYPE OR PRINT NAME Maria L. Perez TELEPHONE NO. 915/688-0375

(This space for State Use) ORIGINAL SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE NOV 22 1989

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:-