	15/
Submit 3 Copies To Appropriate District State of New Mexico	Form C 103
Office District I Energy, Minerals and Natural Resources	Form C-103 Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION	30-015-23377
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	5. Indicate Type of Lease
District IV 2040 South Pacheco, Santa Fe, NM 87505 Santa Fe, NM 87505	STATE X FEE
	6. State Oil & Gas Lease No. E-5229
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM CATALOGUE)	7 I agas Name a II is A
PROPOSALS.)	James Ranch Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM COLUMN 1809 200 CH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	James Raffell Offic
Other Assessment Asses	O WHAT
2. Name of Operator Bass Enterprises Production Co. RECEIVED	8. Well No.
3. Address of Operator D. O. Poy 3760 Median d. TV 70700 0760	9. Pool name or Wildcat
P.O. Box 2760 Midland, 1X 79702-2760	Los Medanos (Atoka)
4. Well Location	
Unit Letter E: 1980' feet from the North I the and	920 feet from the West line
	inic
Section 36 Township 22S Range 30E 10. Elevation (Show whether DR, RKB, RT, GR,	NMPM County Eddy
10. Elevation (show whether DR, RKB, RT, GR,	etc.)
11. Check Appropriate Box to Indicate Nature of Notic	e Report or Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	_
PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB	ABANDONMENT
OTHER: OTHER: Tempora	nily Abandon
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.	ch wellbore diagram of proposed completion
MIRU Plugging Co. RU kill truck, kill well, ND WH, NU BOP's 2-3/8"	Nine rame
Release packer & TOH with 2-3/8" tubing & LD packer.	
RU tubing testers, test tubing in hole open ended to 3000#. PU extra tubing and tag CIBP @	
13,000'. Prep to spot cement plugs.	
Notify Mike Stubblefield w/OCD prior to spotting plugs. All plugs a with a $1.06\ \text{ft}^3/\text{sx}$ yield w/50% excess.	are 15.2 ppg Class H cement
with a 2100 to 075% great w/50% excess.	Temporary Abandoned Status approved
Plug 1: 25 sx, on CIBP @ 13,000'.	until 8-2-07
Plug 2: 25 sx, 11,728-12,025'. WOC, Tag TOC @ 11,680'.	<u> </u>
Plug 3: 45 sx, 10.695-11.055', WOC, Tag TOC @ 10.660'. Mike Bratcher w/OCD notified of MIT. Pressure casing to 510 psi for	20 minutes blad ass 5 min
in 30 minutes. Gerry Guye witnessed MIT. Well TA'd 8/2/02.	30 minutes, pred off 5 ps1
I hereby certify that the information above is true and complete to the best of my knowledge and beli	ef.
Dami Willer	
	<u>DATE 8/15/02</u>
Type or print name Tami Wilber (This areas for State use)	Telephone No. 915-683-2277
(This space for State use)	AUG 2 1 2002
APPROVED BYTITLEConditions of approval, if any:	DATE OF 1 FOOF



