

cc: JOHN
2-17

HALLIBURTON DIVISION LABORATORY

HALLIBURTON SERVICES

ARTESIA DISTRICT

LABORATORY REPORT

No. W51-93

TO Bettis, Boyle & Stovall
P. O. Box 1240
Graham, TX 76450

Date February 10, 1993

This report is the property of Halliburton Services and neither it nor any part thereof, nor a copy thereof, is to be published or disclosed without first securing the express written approval of laboratory management. It may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Services


Submitted by _____ Date Rec. February 9, 1993

Well No. Lotus A Federal #1 Depth 14,912' Formation Morrow

Field _____ County _____ Source _____

Resistivity	<u>0.101 @ 70°</u>		
Specific Gravity ..	<u>1.0562 @ 70°</u>		
pH	<u>7.5</u>		
Calcium	<u>3,969</u>		
Magnesium	<u>624</u>		
Chlorides	<u>48,000</u>		
Sulfates	<u>800</u>		
Bicarbonates	<u>305</u>		
Soluble Iron	<u>250</u>		

Remarks:


Respectfully submitted

Analyst: Eric Jacobson - Operations Engineer

HALLIBURTON SERVICES

NOTICE:

This report is for information only and the content is limited to the sample described. Halliburton makes no warranties, express or implied, as to the accuracy of the contents or results. Any user of this report agrees Halliburton shall not be liable for any loss or damage, regardless of cause, including any act or omission of Halliburton, resulting from the use hereof