

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87501

JUN 6 '90

WELL API NO.

30-015-26350

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Carrasco 14

8. Well No.

3

9. Pool name or Wildcat

E. Loving Delaware)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

RB Operating Company

3. Address of Operator

2412 N. Grandview, Suite 201, Odessa, Texas 79761

4. Well Location

Unit Letter H : 1980 Feet From The North Line and 560 Feet From The East Line

Section 14

Township 23S

Range 28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

2964. GR.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/5/90 Spud 12-1/4" hole, set 8-5/8" 23# J-55 casing @ 539'. Cemented w/450 sxs Class "C" w/2% CaCl, WOC 12 hours.

5/16/90 Drill 7-7/8" hole to 6330', set 5-1/2" 15.5# J-55 casing @6330' w/DV tool @3516'. Cement 1st. stage w/400 sxs 50/50 Pozmix & 150 sxs Class "C" neat. Second stage w/700 sxs 65/35 Pozmix & 100 sxs Class "C" neat circulate 17 sxs to surface.

5/22/90 Clean out to 6280' PBTD. Perforate 6112-22, 6130-42, 6148-52. Acidized w/1500 gals. 10% NeFe & fraced w/25,500 gals. 50,000# sand. Screened out with 8 bbls. flush left to pump.

5/24/90 Cleaned out to PBTD. Set 2-7/8" tubing @ 6096'. Swab & flow testing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE F.D. Schoch TITLE Area Manager

DATE 6/4/90

TYPE OR PRINT NAME F.D. Schoch

(915)
TELEPHONE NO. 362-6302

(This space for State Use)

For Record Only

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: Need Press Test on 8 5/8" Csg