

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 87010
District III
1000 Rio Brazos Rd., Aztec, NM 87401
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL & GAS CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 20-015-26536

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No. 1

7. Lease Name or Unit Agreement Name:
CANDELARIO "24"

8. Well No. 1

9. Pool name or Wildcat
E. LOVING (BRUSHY CANYON)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
RAM ENERGY, INC. 1 018890

3. Address of Operator
5100 E. SKELLY DR., STE. 650, TULSA, OK 74135

4. Well Location

Unit Letter D : 660 feet from the NORTH line and 660 feet from the WEST line
Section 24 Township 23S Range 28E NMPM County EDDY

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: PLUG BACK & RECOMPLETE ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

A. MIRR USH. PULL PUMP & RODS. NU POP. PULL TBG.
B. SET CIPB AT 5660'. PERFORATE BRUSHY CANYON FROM 5456-5574' OVERALL W/4" CSG GUN, 2 SPT
C. RUN TBG & PKR. ACIDIZE W/12% HCL. SINAS LEAD. FROM TREAT. PULL PKR & TBG.
D. RUN TBG W/MA, SN & TAC. ND POP. RUN RODS & PUMP. PUT ON PUMP. PUT WELL BACK ON.
WORK STARTS 11/11/02.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Kaiser TITLE OP ENGR DATE 11/14/02
Type or print name MIKE KAISER Telephone No. (918) 663-2800

(This space for State use)
APPROVED BY TIM W. GUM ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR TITLE DATE NOV 12 2002

Conditions of approval, if any: