

+ c/s
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

APR 20 1992

O. C. D.

WELL API NO. 30-015-26876
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2705
7. Lease Name or Unit Agreement Name Graham AKB State
8. Well No. 2
9. Pool name or Wildcat Lost Tank Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3550' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter H : 1980 Feet From The North Line and 330 Feet From The East Line Section 2 Township 22S Range 31E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3550' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Intermediate & Production Casing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
4-6-92. Ran 96 joints 8-5/8" 32# HC-80 and J-55 casing set 4206'. Guide shoe set 4206'. Float collar set 4162'. Cemented w/1550 sx PSL "C" + 10#/sx Salt + 5#/sx Gilsonite + 1/4#/sx Celloseal (yield 1.94, wt 12.9). Tail in w/200 sx "C" + 2% CaCl2 (yield 1.32, wt 14.8). PD 1:00 AM 4-6-92. Bumped plug to 2000 psi, released pressure, held OK. Circulated 275 sx to surface. WOC. Drilled out 2:00 AM 4-7-92. WOC 13 hrs. NU and tested to 1000 ps for 15 minutes, OK. Reduced hole to 7-7/8" and resumed drilling.
TD 8400'. Reached TD 4-11-92. Ran 191 joints 5-1/2" 15.5# and 17# J-55 set 8400'. Float shoe set 8400', float collar set 8356'. DV tools set 4479' and 7389'. No marker joints run. Cmt'd in 3 stages as follows: Stage I - 200 sx "H" + 8#/sx CSE + .6% CF-14 + 5#/sx Gilsonite + .35% Thriftylite (yield 1.75, wt 13.5). PD 2:00 AM 4-13-92. Circulated 71 sacks. Circulated DV tool 3 hrs. Stage II - 725 sx "H" + 8#/sx CSE + .5% CF-14 + 5#/sx Gilsonite + .35% Thriftylite (yield 1.82, wt 13.6). PD 6:25 AM 4-13-92. Circulated 123 sacks. Circulated thru DV tool 3 hrs. Stage III - 400 sx Super "C" (yield 2.25, wt 11.5). Tail in w/200 sx "C" Neat (yield 1.32, wt 14.8). PD 10:15 AM 4-13-92. Circulated 65 sx to surface. Bumped plug, held OK. WOC 18 hrs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-20-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT I

APPROVED BY _____ TITLE _____ DATE APR 23 1992

CONDITIONS OF APPROVAL, IF ANY: