## N.M. Oli Cons TIV-Dist, 2 FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.

Form 3160-5 (June 1990)

Signed

(This space for Federal or State office use)

Approved by \_\_\_\_\_\_ Conditions of approval, if any:

**UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 

12/02/02

Date

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.    SUBMIT IN TRIPLICATE	SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT-" for such proposals		NM-43744
1. Type of Well   Gas   Well   Other   Stand Dunes 34 Federal #   Sand			6. If Indian, Allottee or Tribe Name
Solid   Soli	SUBMIT IN TRIPLICATE 34567897077		7. If Unit or CA, Agreement Designation
Pogo Producing Company  3. Address and Telephone No. P. 0. Box 10340, Midland, TX 79702-7340 (915) 685-6700 ARTESIA P. 0. Artesia Artesia Production P. 11 Abandonment Notice Plugging Back P. 0. Artesia Production Plugging Back Pl	Oil Gas Well Well Other		
1650¹ FSL & 330¹ FEL, Section 34, T23S, R31E  11. County or Parish, State Eddy County, NM  12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Notice of Intent   Abandonment   Change of Plans   New Construction   New Construction   New Construction   Plugging Back   Non-Routine Fracturing   Water Shut-Off   Conversion to Injection   Other Add Delaware Pay   Other Parish of Injection   Dispose Water   Non-Routine of making congetion on Wet Completion on Wet Compl	Pogo Producing Company /	& STORIVED	9. API Well No.
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Notice of Intent	P. O. Box 10340, Midland, TX	79702-7340 (915)685-8100 ARTESIA	10. Field and Pool, or Exploratory Area
TYPE OF SUBMISSION  Notice of Intent  Notice of Intent  New Construction  New Construction  New Construction  Non-Routine Fracturing  Recompletion  Non-Routine Fracturing  Water Shut-Off  Casing Repair  Other Add De laware Pay  Dispose Water  Conversion to Injection  Wick Report multiple correlation or West Completion or West Completion or West Completion or West Completion or Recompletion or West Completion or Recompletion or West Completion or West Completion or Recompletion or Recompletion or West Completion or West Completion or Recompletion or Recompletion or West Completion or Recompletion or Recompletion or West Completion or Recompletion o		n 34, T23S, R31E UT. I	11. County or Parish, State
Notice of Intent		i) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA
Recompletion   New Construction   New Construction   New Construction   Plugging Back   Non-Routine Fracturing   Casing Repair   Water Shut-Off   Casing Repair   Water Shut-Off   Conversion to Injection   Altering Casing   Conversion to Injection   Other   Add   Del aware   Pay   Dispose Water   Non-Routine Fracturing   Dispose Water   Dispos	TYPE OF SUBMISSION	TYPE OF ACTION	
Gasing Repair    Casing Repair   Water Shut-Off		Recompletion	
(Note: Report results of multiple completion on Well Completion or Recompletion on Recompletion or Recompletion or Recompletion or Recompletion or Recompletion or Recompletion or Recompletion Report and Log form.)  11/13/02 POOH w/ rods & pump.  11/14/02 TOH w/ tog. Set CIBP @ 7278'. Perf Delaware 7014'-28' w/ 2 spf. Test CIBP to 3000# ok.  11/15/02 Acdz 7014'-28' w/ 1000 gals 7-1/2% acid. Swab.  11/19/02 Frac 7014'-28' w/ 32,500# 20/40 SLC.  11/22/02 Perf Delaware 6904'-08' w/ 2 spf.  11/23/02 RIH w/ RBP & set @ 6950'. Test to 3000# ok. Acdz 6904'-08' w/ 750 gals acid. Swab.  11/26/02 Rel RBP @ 6950'. PUH & reset @ 4697'. Test to 3000# ok. Perf Delaware 4444'-60' w/ 2 spf.  Acdz 4444'-60' w/ 1000 gals 7-1/2% acid. Swab.  11/27/02 Rel RBP @ 4697' & POOH.  Return well to production.	-	Casing Repair Altering Casing	☐ Water Shut-Off ☐ Conversion to Injection
11/13/02 POOH w/ rods & pump. 11/14/02 TOH w/ tbg. Set CIBP @ 7278'. Perf Delaware 7014'-28' w/ 2 spf. Test CIBP to 3000# ok. 11/15/02 Acdz 7014'-28' w/ 1000 gals 7-1/2% acid. Swab. 11/19/02 Frac 7014'-28' w/ 32,500# 20/40 SLC. 11/22/02 Perf Delaware 6904'-08' w/ 2 spf. 11/23/02 RIH w/ RBP & set @ 6950'. Test to 3000# ok. Acdz 6904'-08' w/ 750 gals acid. Swab. 11/26/02 Rel RBP @ 6950'. PUH & reset @ 4697'. Test to 3000# ok. Perf Delaware 4444'-60' w/ 2 spf. Acdz 4444'-60' w/ 1000 gals 7-1/2% acid. Swab. 11/27/02 Rel RBP @ 4697' & POOH. 11/28/02 Return well to production.	40 Pareits Present of the second		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
PETROLSIM PROMEEN	11/13/02 POOH w/ rods & pump. 11/14/02 TOH w/ tbg. Set CIBP @ 7278'. 11/15/02 Acdz 7014'-28' w/ 1000 gals 7-1/. 11/19/02 Frac 7014'-28' w/ 32,500# 20/40 11/22/02 Perf Delaware 6904'-08' w/ 2 spf. 11/23/02 RIH w/ RBP & set @ 6950'. Tes. 11/26/02 Rel RBP @ 6950'. PUH & reset. Acdz 4444'-60' w/ 1000 gals 7-1/. 11/27/02 Rel RBP @ 4697' & POOH.	Perf Delaware 7014'-28' w/ 2 spf. Test CIBP to 3000#/2% acid. Swab. SLC.  t to 3000# ok. Acdz 6904'-08' w/ 750 gals acid. Swab.  @ 4697'. Test to 3000# ok. Perf Delaware 4444'-60' w	* ok.  ***********************************

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Sr. Operation Tech