Form 3160-5 June 19901

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MECHIVED

MAY 2 1 1992

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-45235

not use this	s form for proposals to dril	AND REPORTS ON WELLS  If or to deepen or reentry to a different reserve to the second	6. If Indian. Ailottee or Tribe Name
		IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Type or Well  X Well Well Other			8. Well Name and No.
Santa Fe Energy Operating Partners, L.P.			Pure Gold C-17 Fed #5 9. API Well No.
Address and Telephone No.			30-015-27392
550 W. Texas, Suite 1330, Midland, TX 79701 (915) 687-3551			Sand Dunes, W. (Delaware
Location of Well (Footage, Sec., T., R., M., or Survey Description)  (A), 660' FNL and 330' FEL, Sec. 17, T-23S, R-31E			11. County or Parish, State
			Eddy Co., NM
CHE	CK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE.	REPORT. OR OTHER DATA
	OF SUBMISSION	TYPE OF	
	otice of Intent	Abandonment	Change of Plans
_		Recompletion	New Construction  Non-Routine Fracturing
<u>XX</u> 5	ubsequent Report	Plugging Back Casing Repair	Water Shut-Off
		Altering Casing	Conversion to Injection
	Final Abandonment Notice	Other Ran csg and rel	(Note: Report results of multiple completion on well Completion or Recompletion Report and Log form.)
Describe Propose	d or Completed Operations (Clearly state ace locations and measured and true vert	all pertinent details, and give pertinent dates, including estimated drucal depths for all markers and zones pertinent to this work.)*	ate of starting any proposed work. If well is directionally drilled
5/17/93:	TD at 8100'. Prep	to log.	
5/18/93:	Logging.		
5/19/93:	Cemented 1st stage	5-1/2" 15.5 & 17.C# K-55 LT&C caw/ 560 sx "H" + 0.8% FL25 and 5% tail w/ 400 sx Neat.	sing and set at 8100'. KCl. Cemented 2nd stage
5/19/93: 5/20/93:	Cemented 1st stage w/ 200 sx Lite and Set slips w/ 115,00	w/ 560 sx "H" + 0.8% FL25 and 5% tail w/ 400 sx Neat. 00#. Test head to 3000 psi - oka	KC1. Cemented 2nd stage
	Cemented 1st stage w/ 200 sx Lite and	w/ 560 sx "H" + 0.8% FL25 and 5% tail w/ 400 sx Neat. 00#. Test head to 3000 psi - oka	KC1. Cemented 2nd stage
5/20/93:	Cemented 1st stage w/ 200 sx Lite and Set slips w/ 115,00	w/ 560 sx "H" + 0.8% FL25 and 5% tail w/ 400 sx Neat.  00#. Test head to 3000 psi - oka 00 a.m. WOCU.	KC1. Cemented 2nd stage
5/20/93:	Cemented 1st stage w/ 200 sx Lite and Set slips w/ 115,00 Released rig at 3:0	w/ 560 sx "H" + 0.8% FL25 and 5% tail w/ 400 sx Neat.  00#. Test head to 3000 psi - oka 00 a.m. WOCU.	KC1. Cemented 2nd stage