---rm 3160-5 June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

AUG 1 6 1993

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. NM-45235

O. C. D.

not use this f	orm for proposals to dri	AND REPORTS ON WELLS If or to deepen or reentry to a different reserv R PERMIT—" for such proposals	6. If Indian, Ailottee or Tribe Name OIF.
	<del></del>	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
pe of Weil Gas			8. Well Name and No.
Santa Fe Energy Operating Partners, L.P.			Pure Gold C-17 Fed #13
			9. API Well No.
enderess and Telephone No			30-015-27501  10. Field and Pool, or Exploratory Area
550 W. Texas, Suite 1330, Midland, TX 79701 (915) 687-3551			Los Medanos (Delaware
ocation of Well (Footage, Sec., T. R., M., or Survey Description)			11. County or Parish. State
(M), 330' FSL and 730' FWL, Sec. 17, T-23S, R-31E			
			Eddy Co., NM
CHECK	APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
	F SUBMISSION	TYPE OF AC	
<del></del>		Abandonment	Change of Plans
Nouc	ce of intent	Recompletion	New Construction
XX Subs	equent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off Conversion to Injection
Fina	Abandonment Notice	Altering Casing  X Other Ran casing & rel	
		rig	(Note: Report results of multiple compietion on a Completion or Recompletion Report and Log for
		all pertinent details, and give pertinent dates, including estimated date	of starting any proposed work. If well is directionally d
Describe Proposed of give subsurface	r Completed Operations (Clearly state locations and measured and true ver	all pertinent details, and give pertainent details work.)	
8/10/93:	5-1/2" 15.5 and 1 tool at 5940'. C	Logging 2nd run. LD DP and DC. $7.0\#$ K-55 and J-55 LT&C casing and demented 1st stage $w/$ 475 sx "H" + 0 p.m. Floats held. Drop bomb and pit, full returns).	set at 8004'. Stage .8% FL-25 and 5% KCl.
8/11/93:	Plug down at 2:00	ge w/ 125 sx "C" Lite (35:65:6). To A.M. Set slips w/ 110,000#. Cut Test to 3000 psi. Released rig at	off 5-1/2" csg and
	Plug down at 2:00 NU tubing head.	) A.M.  Set slips w/ 110,000#.  Cut	off 5-1/2" csg and 6:00 A.M. CST. WOCU.
4. Thereby certify the Signed	Plug down at 2:00 NU tubing head.	A.M. Set slips w/ 110,000#. Cut Test to 3000 psi. Released rig at	off 5-1/2" csg and 6:00 A.M. CST. WOCU.