

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

30-015-27980

AUG 31 '94

WELL API NO. Not assigned
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Sylvester
8. Well No. 1
9. Pool name or Wildcat Wildcat (Delaware)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> X OTHER Dry Hole	
2. Name of Operator Santa Fe Energy Operating Partners, L.P.	
3. Address of Operator 550 W. Texas, Suite 1330, Midland, Texas 79701	
4. Well Location Unit Letter <u>P</u> : <u>330</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>35</u> Township <u>24S</u> Range <u>28E</u> NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2950' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/22/94: TD 7-7/8" hole @ 5200'. Log.

7/23/94: POH & laydown DC's. TIH open ended and spot cement plugs as follows:

Set Plug No. 1 w/ 50 sx Cl "C" Neat @ 3500'-3600'.
Set Plug No. 2 w/ 40 sx Cl "C" Neat @ 2600'-2700'.
Set Plug No. 3 w/ 50 sx Cl "C" Neat @ 2350'-2450'.
Set Plug No. 4 w/ 75 sx Cl "C" + 2% CaCl₂ @ 550'-700'. Circ'd 2 hrs & tag plug @ 481'.
Set 30' surface plug. LD DP. ND & cut off 8-5/8" casing. Weld on Dry hole marker. Jet & clean pits. Released rig @ 5:00 p.m.

Well plugged and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 7/28/94
TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

APPROVED BY [Signature] TITLE Chief As DATE 2/8/95

CONDITIONS OF APPROVAL, IF ANY: