MINIMUM BLOWOUT PREVENTER REQUIREMENTS

3,000 phi Working Pressure

3 MWP

STACK REQUIREMENTS

No.	Item		Min. I.O.	Min. Nominal
1	Flowline			
2	Fill up line			2-
3	Drilling nipple			
5	Two single or one dual hyd. operated rams			
6a	Orilling spool with 2" min.) 3" min chake line outlets		-	
65	2" min. kill line and 3" min. choks line outlets in ram. (Alternate to 6a above.)			
7	Valve	Gate [] Plug []	3-1/8"	
8	Gate valve—power operated		3-1/8"	
9	Line to choke manifold			3*
10	Valves	Gate [] Plug []	2-1/16*	
11	Check valve		2-1/16*	
12	Casing head			
13	Valve	Gate 🗆 Plug 🗆	1-13/16*	
14	Pressure gauge with needle valve			
15	Kill line to rig mud pump manifold			2*

3

CONFIGURATION

OPTIONAL						
16	Flanged valve	1-13/16"				

CONTRACTOR'S OPTION TO FURNISH:

- All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 3,000 psi, minimum.
- Automatic accumulator (80 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closedagainst full rated working pressure.
- 3.80P controls, to be located near drillers position.
- 4. Kelly equipped with Kelly cock.
- 5.Inside blowout prevventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- 6.Kelly saver-sub equipped with rubber casing protector at all times.
- 7.Plug type blowout preventer tester.
- 8. Extra set pipe rams to fit drill pipe in use on location at all times.
- 9. Type RX ring gaskets in place of Type R.

MEC TO FURNISH:

1.Bradenhead or casinghead and side valves.

GENERAL NOTES:

- 1.Deviations from this drawing may be made only with the express permission of MEC's Drilling Manager.
- 2.All connections, valves, littings; piping, etc., subject to well or pump pressure must be flanged (sultable clamp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through chore. Valves must be full opening and suitable for high pressure mud service.
- Controls to be of standard design and each marked, showing opening and closing position.
- 4. Chokes will be positioned so as not to hamper or delay changing of choke beans. Replaceable parts for adjustable choke, other bean sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- 5.All valves to be equipped with handwheels or handles ready for immediate
- 6.Choke lines must be suitably anchored

- 7. Handwheels and extensions to be connected and ready for use.
- Valves adjacent to drilling spool to be kept open. Use outside valves except for emergency.
- All seamless steel control piping (3000 psi working pressure) to have flexible joints to avoid stress. Hoses will be permitted.
- Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine fill-up operations.

Exhibit 1