




- Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAYOUT PLAN

POGO PRODUCING COMPANY
GETTY "24" FEDERAL # 13
UNIT "O" SECTION 24