

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)

Form approved
Budget Bureau No. 42-R1424
1. LEASE DESIGNATION AND SERIAL NO.

070869A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1830' FSL & 330' FEL of Sec. 26,
T-26-S, R-31-S Eddy County, New Mexico

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

E. D. White Fed. NCT-1

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Mason,
North Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 26,
T-26-S, R-31-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3120' (GR)

O. C. C.
ARTESIA, OFFICE

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

(Other) Deepen in Same Zone

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods & pump. Install BOP. Pull Tubing.

2. Deepen 50' to 4188'. Log Well.

3. Set packer @ 4060'.

4. Acid/Frac Open Hole 4112'-4188' w/2400 gals. 15% NE Acid & 18,000 gal. Emulsifrac containing 25# Adomite & 2# 20/40 Sand per gallon in 6 equal stages using 70# Unibead between stages.

5. Flush w/Lease Crude.

6. Swab.

7. Install production equipment. Test & return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE 6-24-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

JUN 28 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO