

UNITED STATES DEPARTMENT OF THE INTERIOR, GEOLOGICAL SURVEY

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO. NM-0472258 22207

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL [X] GAS WELL [] OTHER []

2. NAME OF OPERATOR Alpha Twenty-One Production Company

3. ADDRESS OF OPERATOR 2100 First National Bank Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1877' FNL and 1650' FWL

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Cities Federal

9. WELL NO. 4

10. FIELD AND POOL, OR WILDCAT Washington Ranch - Delaware

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 34, T25S, R24E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3715 Ground Level

12. COUNTY OR PARISH Eddy

13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON* [X] REPAIR WELL [] CHANGE PLANS [] (Other) []

SUBSEQUENT REPORT OF:

WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT* [] (Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to Plug and Abandon this well using the following procedure:

- Set CIBP at 1300' and dump 35' of cement on top. Place 15 sacks cement plug at the surface. Erect monument at wellsite.

(Temperature survey shows top of cement on production string at 400'.)

** Perforate 75 ft. below surface casing shoe and squeeze with 100 sacks of cement.



OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Executive Vice President DATE September 18, 1981

(This space for Federal or State office use) APPROVED (Orig. Sgd.) PETER W. CHESTER

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

SEP 24 1981

FOR JAMES A. GILLHAM* See Instructions on Reverse Side DISTRICT SUPERVISOR