

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CCD - Artesia

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

CISF

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other	5. Lease Serial No. NM 19423
2. Name of Operator Bill & Patsy Rich	6. If Indian, Allottee or Tribe Name
3a. Address 2401 MARTIN LANE CHARLSBAD, NM	7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) (505) 887-3928	8. Well Name and No. H-M Federal #1
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14, T-25S, R-26E 330 FNL & 560 FEL	9. API Well No. 30-015-21914
	10. Field and Pool, or Exploratory Area Undesignated Aclawire
	11. County or Parish, State Eddy

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See Attached

RECEIVED
2002 FEB 22 AM 10 43
BUREAU OF LAND MGMT.
CHARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Bill Rich

Title *Owner*

Signature

Bill Rich

Date *2/22/02*

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

[Signature]

Title

Date *2/22/2002*

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the subject lease

Office *CFO*

Accepted for record

FEB 22 2002

only

ime for any person knowingly and willfully to make to any department or agency of the United y matter within its jurisdiction.

Bill + PATSY RICK
HM Federal #1
Sec 14, T-25S, R-24E
330 FNL + 560 FEL
Eddy County, NM

P + A Procedure

1. RUPU, POOH w/ rods + pump Lay down rods
2. NU BOP + POOH w/ TBG, RU Wire Line + SET CIBP @ 1900' QAP w/ 35' CMT
3. ND BOP, free point $4\frac{1}{2}$ " CSG + CUT 50' Above free point
4. POOH w/ $4\frac{1}{2}$ " CSG + Lay down
5. TIH w/ TBG + Circ hole w/ 10" SMT 9c1
6. SET 255x CMT plug ~~50'~~ ^{50'} Above + below $4\frac{1}{2}$ " STUB
7. SET 255x CMT plug @ $8\frac{5}{8}$ " ~~STUB~~ ^{Shoe} ~~50'~~ ^{50'} Above + below 205' TO 105'
8. CUT OFF Well head + SET 105x surface plug w/ 4" P + A marker 4' above ground level w/ well information welded on marker including P + A date
9. Clean location rip + seed w/ required seeds.

Hill Federal #1
 Sec. 14, T-25S, R-26E
 330 FNL + 500 FEL
 Eddy County NM

Proposed FFA

105x surface
 Plug

50' minimum

255x surface
 Plug 205' to 105'

12 1/4" hole WOC & tag plug

8 5/8" 24# @ 155' Cmt Cir

255x STUB
 Plug 50' Above
 + below STUB

WOC & tag plug

← 200' to 100' CBL

CIBF 200' to 100'
 CAP W/ 25' CBL

Perforations 1944' - 48'
 1952' - 34'

4 1/2" 9.5# @ 2020' 7 1/2' hole
 Cmt W/ 155x