UNITED STATES						
DEP	ARTMEN	F	THE	INTERIOR		
e e mode	GEOLOGI	CAL	SUF	RVEY		

	7. UNIT AGREEMENT NAME				
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNEL AGREEMENT NAME				
to proposals to drill or to deepen or plug back to a interest	8. FARM OR LEASE NAME				
(Do not use this form for proposals,) reservoir. Use Form 9–331–C for such proposals.)	Washington Ranch Storage Project				
1. oil gas other Gas Storage Well	9. WELL NO.				
Well					
2. NAME OF OPERATOR El Paso Natural Gas Co. /	10. FIELD OR WILDCAT NAME				
3. ADDRESS OF OPERATOR	Washington Ranch Morrow				
1900 Wilco Bldg Midland, Texas 7970l	11. SEC., T., R., M., OR BLK. AND SURVEY OR				
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	Sec, 34, T-25-S, R-24-E				
halow)	12. COUNTY OR PARISH 13. STATE				
AT SURFACE: 1154' FSL & 572' FWL	Eddy N. Mexico				
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	14. API NO.				
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,					
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) GR-3731				
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:					
TEST WATER SHUT-OFF					
FRACTURE TREAT	D 8Y				
SHOOT OR ACIDIZE REPAIR WELL [X]	(NOTE: Repert results of multiple completion or zone				
PULL OR ALTER CASING []	charge on Form 9–330.)				
MOLHALE COMPETITE OF					
The state of the s					
(other) "RTESIA,					
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and it to this work.)*				
1.) Move in and Rig up workover unit, set tu					
2.) Remove wellhead and install BOP.					
	· · · · · · · · · · · · · · · · · · ·				
3.) Pull production tubing with snubbing unit.					
4.) Run permanent packer on wireline and set +100' above perfs.					
5.) Run production tubing, circulate treated packer fluid.					
6.) Land tubing with latch in sub in packer, remove BOP, install wellhead.					
7.) Remove tubing plug, release workover un- Subsurface Safety Valve: Manu. and Type	it, return to service. Set @Ft.				
18. I hereby certify that the foregoing is true and correct					
SIGNED . JE. Myenfitte Sr. Production	Eng. DATE June 15, 1984				
(This space for Federal or State office use)					
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:					

5. LEASE

NM-22207

6. IF INDIAN, ALLOTTEE OR TRIBE NAME