

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Drive  
Santa Fe, NM 87505  
MAR 2004  
OIL CONSERVATION DIV.  
DIST. 3

Form C-103  
Revised May 08, 2003

WELL API NO. <b>30-045-23031</b>	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name: <b>BOLACK J</b>	
8. Well Number <b>1</b>	
9. OGRID Number <b>167067</b>	
10. Pool name or Wildcat <b>W KUTZ PC / BASIN FTC</b>	
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator <b>XTO Energy Inc.</b>	
3. Address of Operator <b>2700 Farmington Ave., Bldg. K. Ste 1 Farmington, NM 87401</b>	
4. Well Location Unit Letter <b>J</b> : <b>1450</b> feet from the <b>SOUTH</b> line and <b>1450</b> feet from the <b>EAST</b> line Section <b>28</b> Township <b>27N</b> Range <b>08W</b> NMPM County <b>SAN JUAN</b>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>6314'</b>	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

XTO Energy Inc. proposes to P&A this well in the following manner:

- 1) Notify BLM & NMOC 24 hrs in advance of pending operations.
- 2) Test rig anchors. Dig & line blow down pit.
- 3) MIRU A-Plus Well Serv rig. Kill well w/wtr if necessary. TOH w/rods & pmp. ND WH. NU BOP.
- 4) TOH. Visually inspect & tally tbg. PU work string if necessary. TIH & tag CIBP @ 1870'. Load wellbore w/wtr & establish circulation.
- 5) Mix 32 sx Type II cmt (in two stages) and spot cmt fr/1870'-770' to cover PC, FTC perms & the Ojo Alamo top. PUH & WOC. TIH & tag cmt. TOH & LD tbg.
- 6) RIH & perf 2 squeeze holes @ 128'. Establish circulation out of bradenhead. Mix & pmp 25 sx Type II cmt dwn 2-7/8" csg to circ cmt out of bradenhead vlv. SI well & WOC.
- 7) ND BOP. Cut off WH below surf csg. Install P&A marker. RDMO A Plus Well Service.
- 8) Haul all equipment to XTO yard. Reclaim loc per BLM specs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Holly C. Perkins TITLE REGULATORY SPECIALIST DATE 2/27/04

Type or print name HOLLY C. PERKINS

Telephone No. 505-324-1090

(This space for State use)

APPROVED BY Charles L. TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3 DATE MAR - 1 2004

Conditions of approval, if any: