Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Lease Serial No.
Lease Senai No.
NOO 0050 4400
NOG-0652-1132

6.	If Indian, Allottee or Tribe Name	
	NAVAJO	

SUBMIT IN TRI			7 ISIInia CA/A	
1 Time of Well	PLICATE - Other instruc	tions on reverse side	7. II Onlt of CAVAgr	eement, Name and/or No.
1. Type of Well	her	-2 000	8. Well Name and No HUERFANITO L	
2. Name of Operator BURLINGTON RESOURCES	Contact:	PEGGY COLE E-Mail: pbredfield@br-inc.com	9. API Well No. 30-045-06358	
a. Address 3401 EAST 30TH FARMINGTON, NM 87402		3b. Phone No. (include area code Ph: 505.326.9727 Fx: 505.326.9563	10. Field and Pool, o	or Exploratory CRA/BLANCO PC
1. Location of Well (Footage, Sec., 1 Sec 24 T27N R9W NESW 18		V / 1	11. County or Parish SAN JUAN CO	•
12. CHECK APP	ROPRIATE BOX(ES) TO) INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION		ТҮРЕ О	TYPE OF ACTION	
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Of
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	☐ Well Integrity
Subsequent Report ■ Subsequent Report Subsequent Report	☐ Casing Repair	■ New Construction	Recomplete	Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	□ Temporarily Abandon	•
	☐ Convert to Injection	Plug Back	□ Water Disposal	
NU BOP. TIH. Spot 30 gals 2 holes total. TOOH. TIH. Tage (01/07/03) MIRU. Frac PC w/	ged CIBP @ 2204'. Circ w 312 bbls 10# linear gel 85	/ooh. TH. Perf PC @2070 /air. TOOH. ND BOP. NU W 000# 20/40 brady , 15000# 1	H. RD. Rig Released. 2/20 brady sd	
301,300 scfN2. Flow Back (01/09/03) Flow Back. (01/10/03) Flow Back. RD (01/31/03)MIRU. ND WH. NU (02/01-02/03) Flow & Blow. (02/03/03) TOOH. TIH. Set R		_		· ·
301,300 scfN2. Flow Back (01/09/03) Flow Back. RD (01/10/03) Flow Back. RD (01/31/03)MIRU. ND WH. NU (02/01-02/03) Flow & Blow. (02/03/03) TOOH. TIH. Set R	BP @ 30'. ND BOP, NU B	BOP. TIH, tag up. No fill. TOC	OH. TIH w/71 jts 2	
301,300 scfN2. Flow Back (01/09/03) Flow Back. RD (01/10/03) Flow Back. RD (01/31/03)MIRU. ND WH. NU (02/01-02/03) Flow & Blow. (02/03/03) TOOH. TIH. Set R	S true and correct. Electronic Submission & For BURLINGTON RES	30P. TIH, tag up. No fill. TOC \$17108 verified by the BLM We DURCES OIL & GAS, will be se	OH. TIH w/71 jts 2	
301,300 scfN2. Flow Back (01/09/03) Flow Back. (D. (01/10/03) Flow Back. RD (01/31/03) MIRU. ND WH. NU (02/01-02/03) Flow & Blow. (02/03/03) TOOH. TIH. Set R	S true and correct. Electronic Submission & For BURLINGTON RES	30P. TIH, tag up. No fill. TOC \$17108 verified by the BLM We DURCES OIL & GAS, will be se	OH. TIH w/71 jts 2 Ill Information System ent to the Farmington RT AUTHORIZER	
301,300 scfN2. Flow Back (01/09/03) Flow Back. (01/10/03) Flow Back. RD (01/31/03) MIRU. ND WH. NU (02/01-02/03) Flow & Blow. (02/03/03) TOOH. TIH. Set R	IS true and correct. Electronic Submission & For BURLINGTON RESCOLE	SOP. TIH, tag up. No fill. TOO 217108 verified by the BLM We OURCES OIL & GAS, will be so	OH. TIH w/71 jts 2 Ill Information System ent to the Farmington RT AUTHORIZER	
301,300 scfN2. Flow Back (01/09/03) Flow Back. (D1/10/03) Flow Back. RD (01/31/03) MIRU. ND WH. NU (02/01-02/03) Flow & Blow. (02/03/03) TOOH. TIH. Set R	IS true and correct. Electronic Submission & For BURLINGTON RESCOLE	BOP. TIH, tag up. No fill. TOO #17108 verified by the BLM We OURCES OIL & GAS, will be so Title REPO Date 02/13/	OH. TIH w/71 jts 2 Ill Information System ent to the Farmington RT AUTHORIZER	

Additional data for EC transaction #17108 that would not fit on the form

32. Additional remarks, continued

3/8" 4.7# J-55 EUE tbg, landed @ 2065. SN @2063. ND BOP. NU WH. RD Rig Released.

