

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-045-23608</b>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE FEE <input checked="" type="checkbox"/>
2. Name of Operator <b>BP America Production Company</b> Attn: Mary Corley		6. State Oil & Gas Lease No.
3. Address of Operator <b>P.O. Box 3092 Houston, TX 77253</b>		7. Lease Name or Unit Agreement Name: <b>Jacques</b>
4. Well Location Unit Letter <b>E</b> <b>1830</b> feet from the <b>North</b> line and <b>1135</b> feet from the <b>West</b> line Section <b>25</b> Township <b>30N</b> Range <b>09W</b> NMPM <b>San Juan</b> County		8. Well No. <b>3</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>5664' GR</b>		9. Pool name or Wildcat <b>Blanco Pictured Cliff</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: **Abandon the Dakota & Bradenhead Repair** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/30/2003 MIRUSU. Check & pressures. Blow down well. Kill w/2% KCL WTR. NDWH. NU BOPs. TOH w/1 1/4" production TBG. TOH w/2 3/8" production TBG. TIH w/PKR plucker, remove PKR set @ 2700' & TOH. TIH w/4 1/2" CIBP & Set @ 6623'. RU & spot 100' CMT plug from 6523' - 6623'. TOH. RU, TIH w/7" RBP & set @ 2321'. Load hole w/ 2% KCL & pressure test CSG to 500#. Held Ok. RU & shot 4 SQZ holes @ 1125'. TIH & set PKR @ 940'. SQZ 300 SXS CMT. SQZ did not come thru bradenhead. RU & ran CBL from 30' - 1030'. RU & shot 4 SQZ holes @ 280'. TIH w/PHR & set @ 173'. RU & SQZ 75 SXS CMT. Circulated CMT to surface. Unseat PKR & TOH. TIH & tag CMT @ 207'. DO CMT to 280'. Circ hole clean. Pressure test squeeze to 500 psi. Test Ok. TIH & tag CMT @ 1037'. DO CMT to 1140'. Circ hole clean. Loaded hole & pressure test CSG to 500 psi. Test Ok. TIH & tagged fill @ 2315'. C/O to top of RBP set @ 2321'. Circ hole clean. Unseat RBP & TOH. TIH w/scrapper & work thru perms. TOH TIH w/2 3/8" production TBG & land @ 2402'. ND BOPs. NUWH. Test well for air.

RDMOSU 02/14/2003 Return well to production as a single Blanco Pictured Cliffs producer.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Corley TITLE Sr. Regulatory Analyst DATE 02/21/2003

Type or print name Mary Corley Telephone No. 281-366-4491

(This space for State use)

APPROVED BY Charles H. TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #2 DATE FEB 24 2003

Conditions of approval, if any: