

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

2003 JAN 22 PM 1:03

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Roddy Production Company, Inc.

3. Address and Telephone No.

P. O. Box 2221, Farmington, NM, 87499 505-325-5750

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1250'FNL - 2035'FEL, Section 19, T31N, R12W, NMMP

5. Lease Designation and Serial No.
SF078243

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Owen No. 2B

9. API Well No.
30- 045 - 31146

10. Field and Pool, or Exploratory Area
Blanco Mesa Verde

11. County or Parish, State
San Juan Co., New Mexico

12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☒ Casing Repair
☐ Altering Casing
☐ Other _____
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to evaluate this well for repair or plug and abandon by the following procedure. Move in completion unit. Drill cement out of casing from 93' to 5109'. Run CBL to determine top of cement behind 4 1/2" casing. Design squeeze to cover remaining Mesa Verde interval and upper casing section. If upper Pt. Lookout has taken cement from original cement job, perforate and acidize through packer to determine damage to zone. Determine remainder of procedure based on these results. If costs are not prohibitive, casing is not damaged and zone is not damaged, will perform remedial cementing to cover Mesa Verde and upper casing. Proceed with completion attempt. If casing is damaged or zone is damaged from original cement job, will propose a plug and abandonment procedure.

14. I hereby certify the foregoing is true and correct

Signed *Robert E. Fildes*

Title Agent

Date January 20, 2003

(This space for Federal or State office use)

JAN 22 2003

Approved by **/s/ Jim Lovato**
Conditions of approval, if any:

Title _____

Date _____

NMCCD

Current Configuration

TOC inside casing - 93'

8 5/8" 24# set @
309'

12 1/4" Off TO
316

478' ojo Alamo

553' Kirtland

.Screw in sub at 1113'-not completely made up?

1797' Fruitland

2113' Basal FC

2206 PC

2374' Lewis

DY Tool @ 3465'

M
U
D

3852 Cliff House

4078 Menefee

4640 Pt. Lookout

Estimated TOC behind 4 1/2 casing - 4810'

4990' Mancos
(?)

FC @ 5109'

4 1/2" 10.5# set at
5156'

77/8' OHTD-5158'