submitted in lieu of Form 3160-5

## **UNITED STATES**

Ĭ	<sub>0</sub> BUR	ARTMENT OF THE EAU OF LAND MAN	NAGEMENT	070 Fa	070 Farmington, NM		
1.	Type of Well WIW		A 57 T	5. 6.	Lease Numb 14-20-603-2 If Indian, All. Tribe Name	<b>er</b> 034	
2.	Name of Operator Hart Oil & Gas, Inc.		By APA 200	<b>7.</b>	Unit Agreem		
3.	Address & Phone No. of Operator PO Box 307, Farmington, NM 8749			8. 9.	Well Name & Navajo TI "I API Well No. 30-045-1104	F" #125	
Lo	cation of Well, Footage, Sec., T, R,	M		<u> </u>	Field and Po	ol	
	660' FSL and 1980' FWL, Section	1, T-31-N, R-17-W,		11.	Horseshoe County & Sta San Juan Co	ate	
12.		Type of Action Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other -	OF NOTICE, REPOR  Change of Pla New Constru Non-Routine Water Shut of Conversion to	ans ction Fracturing off	ATA		
13.	Hart Oil & Gas plugged and a  2-18-04 MOL & RU. PU 33 joints 2-3/ bbls water. Plug #1 with 56 s  2-19-04 Pressure test casing to 500#, 0 circulation out bradenhead with 98' to surface, circulate good of	abandoned this we 8" workstring and tag xs cement from 1037' DK. RIH wireline and n 3 bbls of water. Plug	at 1037'. Establish circ to 397'. TOH and LD t tag cement at 471'. Pe g #2 with 41 sxs cemen	culation out the ubing. Shut in rforate 2 holes t pumped dowr	well and WOC. at 98'. Establish the 5" casing fro	n om	
	3' in 5" casing. Mix 17 sxs cen W. Ashley, Navajo Nation Mine	<del>-</del>			on.		
	ned Gina M. Saied		t. e President		Date	3/1/04	
ÀΡ	is space for Federal or State Office u PROVED BY NDITION OF APPROVAL, if any:	se) Title			Date HEC	Û:	

PR 0 6 2004