

Memorandum

To: Charlie Perrin - NM OCD, Aztec

Date: April 7, 2004

From: Brett Adams

Re: San Juan 28-6 Unit #75 API 30-039-07153

Charlie, this letter is to summarize the meeting Ken Johnson and I had with you yesterday concerning the referenced well.

This well was completed in 1957 with a 5-1/2" liner set from 3150' to 5400'. The wellfile and operations records in this office show this well does not have intermediate casing. A wellbore diagram is attached for your records.

The bradenhead test that Burlington Resources submitted dated 7/26/2001 was filed incorrectly. We speculate that since the wellhead does have a spool for intermediate casing the operator assumed it was in the well. He correctly reported what he measured but there is no intermediate casing in this well.

Also attached for your records is a photo of the wellhead taken 4/06/2004.

Please advise if there is any other information you need.


GIHA

Brett Adams

Production Engineer

Cc: Nancy Oltmanns wellfile

Burlington Resources SJ 28-6 #15 N 03 27N 6W photo as of 4/6/04



tr # 71850 # 4988901 St 28-6 # 75 EPNG PL 750/ FUL 1850/ FWL MV 29,83 NRI Let 36 °35 51.468"N 38,25 WI 18/56 Spud by NWPL long 107° 27' 23,724" W N 03 27N 6W 457 complete SITP 1092 CAOF 4.6 SICP 1106 KB6261' _elev 62571 perf. 5104-5378 (259F) £76Mg 103/411 37.75 # H40 perf 4620-5012 f78Mg Ojo Alamo 2250' 17/57 in 5/28-6 mit 4 EPNG Kirtland 2396' 乙2%4.7世 1/15/61 intermitter installed 5184 2/7/57 Fruitland 2745' Pd 29801 126/78 CP installed Cliff Hse 46081 /1/94 install pite EPNC delug 12/99 install 60 bb fg Tit Menefee 4752' 15054 128/00 install plunger lift Pt. Lookout 5180' sep/fank/DVF #31M X TOL (5020 505X) 31501 32381 2 17%" 24.60# H40 1/26/01 bradelihead 5 psi casing 350 pri 347 Bi interm FTD 128 151 Charlie Perrin -> blew to OTN 6 sec 15054 OCD 3346178 5378 155 14 ± 155 OHTD