\* submitted in lieu of Form 3160-5

### UNITED STATES

## DEPARTMENT OF THE INTERIOR

	<b></b>	BUREAU OF I			<del></del>			who with
	Ϊ́	Sundry Notices	and Repo	rts on Well	s			
					-, -, -, -, -, -, -, -, -, -, -, -, -, -		ease Numb	er
1. Ty	ppe of Well GAS					6. I	f Indian,	
	ame of Operator				100 A	7. <b>u</b>	nit Agree	ment Name
	BURLINGTO RESOURCE		MPANY		100g			
	dress & Phone N		400 (505)	200 (2500)		// s	ell Name chumacher	9
	PO Box 4289, Far	mington, NM 8/	499 (505)	326-9700 		-	<b>PI Well N</b> 0-045-094	
	ocation of Well, 00'FSL, 1650'FWL			PM	4.9.50		<b>rield and</b> Blanco Mes	
							ounty and San Juan C	
	CHECK APPROPRIAT					HER D	ATA	
Ty	<b>rpe of Submissio</b> Notice of	Intent	_ Abandon		_ Change of			
	_X_ Subsequen	t Report	_ Recompl	g Back	_ New Const _ Non-Routi	ne Fra	acturing	
	Final Aba	ndonment	_ Casing _ Alterin _ Other -	g Casing	_ Water Shu _ Conversio			
13.	Describe Propo	sed or Complete	d Operati	ons				_
	Burlington Rese per the	ources performe attached operat			s on the su	ıbject	well as	
								1 mg 1
					AC	CEPTE	D FOR RECO	PD -
						APR	2 0 2004	
			* .		FAR		N FIELD OFFIC	<b>*</b>
					BY_		MAS	
							// <b>U</b>	
							25 ta.	<b>153</b>
14.	I hereby certif	y that the for	egoing is	true and co	orrect.	·		-
Signe				Regulatory		. Date	, 4/7/04	
	space for Feder		· · · · · · · · · · · · · · · · · · ·		Specialist		2/ / / / 3	<u>.</u>
APPRO	VED BY		Title _		Date	·	v	<u>.</u>
Title 18	TION OF APPROVAL U.S.C. Section 1001, make tates any false, fictition	s it a crime for any pers	son knowingly an	d willfully to mak tions as to any ma	e to any departmen tter within its ju	nt or agen	cy of the	

### BURLINGTON RESOURCES

# San Juan Division - Intranet Well Information System (DIMS)

Thursday, April 1, 20

}L000n	By Date	By Well	-By AFE	→ JBy Rig
Printouts	→ Production N	lotes 💌Account	ability 💌Safety-	- 💌
<b>V</b>	Other-	<b>★</b> API U	nits •	

### **Export to Excel**

# Operations Detail Report for: SCHUMACHER #9 FACILITIES

### Entire Well / All Events

Time Breakdown Summary

D.6.32	DAY FROM TO HRS DEPTH PHASE CODES OPERATION							ODEDATION
DAY	FROM	то	пкэ	(ft)	PHASE	CODES		OPERATION
1 (FAC)	01/27/2004 06:00	08:30	2.50		ОВЈЕСТ	SAFE a	N	AWS-BR SAFETY MTG,
1 (FAC)	01/27/2004 08:30	09:30	1.00		ОВЈЕСТ	SRIG a	N	CRANK RIG ROAD TO LOC.
1 (FAC)	01/27/2004 09:00				ОВЈЕСТ	SRIG a	N	ROAD RIG TO LOC.
1 (FAC)	01/27/2004 09:30	11:30	2.00		MIRU	RURD a		ARRIVE ON LOC. SPOT EQUIP. RU RIG, REV UNIT, WELL HISTORY SHOWS SIGNS OF H2S DURING DRILLING OPS. CALLED T&M ENTERP. FOR SAFETY TRILR. AND REP. CALLED FOR FLOWBACK TANK TO DIVERT GAS FROM WELLHEAD. CALLED FOR LOAD OF 2% TO PUT IN RIG PIT.
1 (FAC)	01/27/2004 11:30	12:30	1.00		OBJECT	BLOW a	N	BLEED PRESS OF WELL ISTP=225, ISCP= 325 WAIT ON WATER WHILE BLEEDING OFF WELL.
1 (FAC)	01/27/2004 12:30	13:00	0.50		OBJECT	SAFE a	N	HOLD SAFETY MTG FOR H2S AWARENESS.
1 (FAC)	01/27/2004 13:00	13:45	0.75		ОВЈЕСТ	RURD a		RU FLOWBACK TANK, WATER ARRIVED, PUMPED 20BBLS DWN TBG AFTER UNSEATING PUMP. WELL SHOWING ABOUT 111 PPM H2S. NO WARNING SIGNS OR WIND SOCKS ON WELL SITE FOR DANGER OF H2S. PUMP 20 BBLS DOWN TBG SUPPRESS GAS. DETECTION NOW 10PPM.
1 (FAC)	01/27/2004 13:45	14:30	0.75		ОВЈЕСТ	RURD a		LAYDOWN POLISH ROD RU TO PULL RODS AND PUMP. 233 3/4 RODS 1 1/4 X 22' PR, 2" X 1 1/4 X 14' RHAC-Z PUMP.
1 (FAC)	01/27/2004 14:30	17:00	2.50		OBJECT	PULD a	N	POOH LD RODS AND PUMP.
	01/27/2004	17:45	0.75		ОВЈЕСТ	RURD	N	RD ROD EQUIP. RU TBG EQUIP. SDON.

1 (FAC)	17:00				а		CAMERON WELLHEAD SER. TO BE ON LOC. 0700 TO INSPECT TREE. TREE WILL HAVE TO BE CHANGED OVER TO ACCOMIDATE PLUNGER LIFT PRODUCTION. H2S BOP ALSO TO BE DEL FIRST THING A.M.
2 (FAC)	01/28/2004 06:00	06:30	0.50	OBJECT	SRIG a	N	CREW TRVL TO LOC.
2 (FAC)	01/28/2004 06:30	07:00	0.50	OBJECT	SAFE a		HOLD SAFETY MTG, JHA, H2S AWARENESS, WATCH FOOTING, KEEP WORK AREA CLEAR. CRANK ENGINES.
2 (FAC)	01/28/2004 07:00	07:45	0.75	OBJECT	BLOW a		BLOW WELL DOWN ISTP=225, CISP=325, WELL SHOWS 55 PPM H2S,
2 (FAC)	01/28/2004 07:45	09:00	1.25	OBJECT	PUMP a		PRIME REV. PUMP, PUMP 20 BBLS 2% KCL SUPPRESS H2S TO @ 1PPM.
2 (FAC)	01/28/2004 09:00		<u> </u>	OBJECT	NUND a		NDNU, STRIPPER AND BLOW INE ASSEMBLY OFF AZTEC BOP'S, NU TO HIGH TECH H2S BOP'S
2 (FAC)	01/28/2004 10:00	1		OBJECT	WELH a		REPLACE LOCK AND PACK OFF NUTS ON WELL HEAD DONUT ASSEMBLY,
2 (FAC)	01/28/2004 11:00	12:00	1.00	OBJECT	NUND a	N	NU H2S BOP'S TO WELL.
2 (FAC)	01/28/2004 12:00	13:00	1.00	OBJECT	RURD a	N	RU TO PULL TBG.
2 (FAC)	01/28/2004 13:00	15:00	2.00	OBJECT	PULD a	N	POOH LAYING DOWN OLD PROD STRING. 1- 2 3/8 XCK, 1 JT 2 3/8 TBG, 1 4' 2 3/8 PERF. SUB, 1 S.N, 181 JTS 2 3/8 TBG.
2 (FAC)	01/28/2004 15:00	15:45	0.75	OBJECT	RURD a		HAUL OLD STRING TO BR YARD, MOVE NEW STRING ON FLOAT INTO PLACE. RU TO RIH WITH NEW BLUE BAND STRING.
2 (FAC)	01/28/2004 15:45	17:45	2.00	OBJECT	TRIP a		TIH WITH SAW TOOTH 2 3/8 COLLAR, XCK, 1.780 I.D. S.N. 1 JT 2 3/8, 1-2' 2 3/8 SUB, 168 JTS 2 3/8 TBG, 1 10' 2 3/8 SUB, 1 JT 2 3/8 TBG, SDON
3 (FAC)	01/29/2004 06:00	06:30	0.50	OBJECT	SRIG a	N	CREW TRVL TO LOC
3 (FAC)	01/29/2004 06:30	07:00	0.50	OBJECT	SAFE a		HOLD SAFETY MTG, JHA, H2S AWARENESS, WATCH PINCH POINTS.
3 (FAC)	01/29/2004 07:00	08:00	1.00	OBJECT	BLOW a		BLEED OFF WELL, PUMP 5 BBLS 2% KCL, GAS SUPPRESSED TO 1PPM,
(FAC)	01/29/2004 08:00			OBJECT	TRIP a		TIH WITH REMAINING TBG, PROD STRING CONSITS OF, SAW TOOTH COLLAR, XCK, 1.780 I.D.S.N. 1 JT 2 3/8 TBG, 1 2' SUB, 169 JTS TBG 2 3/8, TBG LANDED AT 5319.20
(FAC)	01/29/2004 10: <b>00</b>		1.00	OBJECT	NUND a		ND BOP, NU WELL HEAD, CAMERON DELIVERED WELL HEAD READY FOR PLUNGER IFT OPS. RELEASE H2S BOP.
3 (FAC)	01/29/2004 11:00	14:00	3.00	RDMO	RURD a		RDMO, NOTIFIED LSE OPR MARK GLOVER RET TO PROD. NOTIFIED FIRST DEL. OF RET TO PROD. AND NO WIND SOCKS OR DANGER SIGNS OF H2S.