submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT				
Sundry Notices and Reports on Wells		·····		
	5.	Lease Nur		
1. Type of Well	6.	NMSF-0785		
GAS		Tribe Nam	ne	
	7.	Unit Agre	eement	t Name
2. Name of Operator BURLINGTON	•.			
RESOURCES OIL & GAS COMPANY				
3. Address & Phone No. of Operator	8.	Well Name HOWELL K		mber
PO Box 4289, Farmington, NM 87499 (505) 326-9700	y 9.	API Well	No.	
4. Location of Well, Footage, Sec., T, R, M	ິ 10.∋ຸ	30-045-3 Field and		L
1025'FNL,1390'FEL, Sec.15, T30N, R8W, NMPM	4 J	BASIN FR	UITLA	ND COA
	Ţĭ.	County a		
		San Juan	Co, 1	M
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	OTHER	DATA		
Type of Submission Type of Action Notice of Intent Abandonment Change				
Recompletion New Con X Subsequent Report Plugging Back Non-Rou		on acturing		
Casing Repair Water S				
Final Abandonment Altering Casing Convers X Other	ion to	Injection	1	
13. Describe Proposed or Completed Operations				
Burlington Resources did workover operations as per attached da	-	070 154	75038 7503 7500 7500	高
ACCEPTED FOR	RECORD			
APR 1 9 20	004	ğ	and the second	
FARMINGTON FIELD BY	OFFICE	Z	33 33	
14. I hereby certify that the foregoing is true and correct. Signed Title Regulatory Special	<u>ist</u> Dat	****	04	
	ate	fsb		
CONDITION OF APPROVAL, if any: Pitle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any depa Jnited States any false, fictitious or fraudulent statements or representations as to any matter within i	rtment or a	gency of the		

BURLINGTON

San Juan Division - Intranet Well Information System (DIMS)

Friday, April 2, 20

Logon	By Date ¥I	By Well	By AFE 👻	By Rig
Printouts	Production Notes	Accountability	-Safety	*
	Other-			

Export to Excel

Operations Detail Report for: HOWELL K #300S FACILITIES

Entire Well / All Events

Time Breakdown Summary

DAY FROM TO HRS DEPTH PHASE CODES OPERATION					OPERATION			
			пкэ	(ft)	FINASE	CODES		OPERATION
1 (FAC)	01/09/2004 06:00	07:00	1.00		PREWRK	MIMO a		ROAD RIG AND CREW TO LOC., LINDSEY COM 250
1 (FAC)	01/09/2004 07:00	07:30	0.50		PREWRK	SRIG a	N	WARM UP RIG, REMOVE CHAINS
1 (FAC)	01/09/2004 07:30	08:30	1.00		PREWRK	MIMO a		ROAD RIG FROM LINDSEY COM 250 TO LOCATION
1 (FAC)	01/09/2004 08:30	08:45	0.25		PREWRK	SAFE a		SAFETY MEETING - TIGHT LOCATION, WELLHEAD, PIPING, LAND FARM, MARK DANGER POINTS WITH RIBBON, BACK CAREFULLY, 5 CREW, RIG SUPERV.
1 (FAC)	01/09/2004 08:30	09:45	1.25		MIRU	MIMO a	N	SPOT RIG, LEVEL FROZEN SOIL FOR PADS, RU RIG
1 (FAC)	01/09/2004 09:45	10:45	1.00		ОВЈЕСТ	NUND a	Z	NDWH, NUBOP, PULL DON UT, PU 2 JOINTS, TAG @ 2785, LD 2 JOINTS PICKED UP OFF TRAILER, LAY DOWN 1 JOINT TUBING & 1 6' PUP OUT OF TUBING STRING, LAND TU BING @ 2715.61, SN @ 2687.87, PBTD @ 2785, PERFS 2481 TO 2695, 5 1/2" 15.5# LINER, LINER TOP 2484, TUBING CONFIG: 1 - 2.375 BULL PLUG 1 - 2.375 EUE PUP JOINT (6') 1 - 3.061 COLLAR SIZE SEPARATOR 1 - 2.375 EUE PUP JOINT (12') 1 - 2.375 SEATING NIPPLE 84 - JOINTS 2.375 EUE J-55 4.7# TUBING 1 - 2.375 EUE PUP JOINT (8') 1 - 2.3 75 EUE PUP JOINT (10') 1 - 2.375 EUE J-55 4.7# TUBINGING
1 (FAC)	01/09/2004 10:45	11:30	0.75		OBJECT	NUND a	N	RIG DOWN FLOOR, NDBOP, NUWH, PREPARE TO INSTALL NEW PUMP AND IRODS
1 (FAC)	01/09/2004 11:30	12:00	0.50		OBJECT	WAIT a	N	WAIT ON PUMP AND RODS
)			

1 (FAC)	01/09/2004 12:00	12:30	0.50	ОВЈЕСТ	NUND a		BREAK OUT MASTER VALV E, NU RADIGAN, FLOW TEE, PIPING
1 (FAC)	01/09/2004 12:30	14:30	2.00	OBJECT	PULD a		PU PUMP, TIH W/FOLLOW ING: 1 - 2" X 1 1/2" X 10 X 14 RWAC-Z DV SV&T V, SCPID-001 BBL, 4SM-003 PLUNGER, TV SN /TC, SV CER/TC A/A VALVES, 99" MAX STROKE , BR745, 3/4" PIN, SANDCHECK, SPIRAL ROD GUIDE LIFT SUB 3 - 1.250 SINKER BARS 103750 SUCKER RODS CLASS "D" PLAIN 4750 PONIES (2, 6, 6, 8) 1 - 1.250 POLISH ROD W/1.500 POLISH ROD LINER 1 - INJECTAPAK STUFFING BOX
1 (FAC)	01/09/2004 14:30	15:30	1.00	OBJECT	PRES a		SPACE OUT, SEAT PUMP, LOAD TUBING W/WATER, PRESSURE TEST TO 1500#, BLEED OFF, LONGSTROKE FROM 200 TO 600#, GOOD PUMP ACTION
1 (FAC)	01/09/2004 15:30	16:15	0.75	OBJECT		N	PURGE ALL LINES TO BACISTIDE OF METER RUN, GET GOOD FUEL TO PUMPING UNIT, START
1 (FAC)	01/09/2004 16:15		0.00	ОВЈЕСТ			RUHH, HANG OFF, SETTAG, PICKUP TOOLS OUT OF THE MUD, SECURE RIG, LEAVE PUMPING UNIT PUMPING TO TANK, NOTIFIED LEASE OPERATOR AND DUANE BICKLER, WILL CHECK ON LOCATION OVER WEEKEND. SDTM 1-12-2004
2 (FAC)	01/12/2004 06:00	07:00	1.00	PREWRK	MIMO a	N	ROAD CREW TO LOC., WA RM UP AND SERVICE RIG
2 (FAC)	01/12/2004 07:00	07:15	0.25	PREWRK	SAFE a	N	SAFETY MEETING - ENVIR ONMENTAL, ALL SPILLS CLEANED UP, NO TRASH LEFT ON LOCATION OR ROAD INTO, 5 CREW, RIG SUPERV., TOOLPUSHER
(FAC)	01/12/2004 07:15	08:00	0.75	RDMO	RURD a	N	RIG DOWN RIG, RELEASE RIG @ 0800 HOURS, LEAVE PUMPING UNIT RUNNING, RAN ALL WEEKEND, MOVE TO HOWELL K 300 PULLED UP ON TUBING, NO FILL, RELAND HIGHER, 11' BELOW BOTTOM PERF, RAN IN HOLE WITH NEW PUMP AND RODS, PURGED ALL LINES, STARTED NEW PUMPING UNIT, LET PUMPING UNIT PUMP OVER WEEKEND, MOVE TO HOWELL K 300 CLEANED UP ALL SPILLS AND TRASH OFF LOCATION

Global Intranet | Comments and Feedback | Legal Notice | Privacy Statement