Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	NMSF078209 <i> </i> B
Do not use this form for proposals to drill or to re-enter an	· ·
bandoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name

abandoned we	II. Use form 3160-3 (APD) fo	or such proposals.	6. If Indian, Allottee	or Tribe Name
SUBMIT IN TRI	PLICATE - Other instruction	s on reverse side.	7. If Unit or CA/Agr NMNM73868	eement, Name and/or No.
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Ot	her	· · · · · · · · · · · · · · · · · · ·	8. Well Name and No GCU 180E	<b>)</b> .
2. Name of Operator	Contact: CHE	RRY HLAVA	9. API Well No.	00.04
BP AMERICA PRODUCTION  3a. Address		ail: hlavaci@bp.com  Phene No. (include area code	30-045-24869-	
P. O. BOX 3092 HOUSTON, TX 77253	Ph Fx	281.366.4081 : 281.366.0700003	BASIN DAKÓT G <del>ALLEGO</del> S G	TA ALLUP
4. Location of Well (Footage, Sec.,	· - ·	E WAR	11. County or Parish	
Sec 28 T29N R12W SESW 0 36.69251 N Lat, 108.10783 V		E OR GARAGE	SAN JUAN CO	DUNTY, NM
12. CHECK APP	ROPRIATE BOX(ES) TO IN	DICATENATURE OF	NOTICE, REPORT, OR OTHE	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
Subsequent Report	☐ Casing Repair	☐ New Construction	Recomplete	Other Subsurface Comming
Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	Temporarily Abandon	Subsurface Comming
	Convert to Injection	☐ Plug Back	☐ Water Disposal	<b>.</b> 6
Basin Fruitland Coal and com Pools. Permission was grant  No perfs were added to the F	ruitland Coal formation. This commingling the Dakota & Gall	with the existing Basin Dasin Da	akota & Gallup	
14. Thereby certify that the foregoing is	Electronic Submission #1844	ODUCTION CO. sent to th	e Farmington	
Name (Printed/Typed) CHERRY			DRIZED REPRESENTATIVE	
Signature (Electronic	Submission)	Date 02/10/2	2003	
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE	
Approved By ACCEPT	ED		W HALBERT EUM ENGINEER	Date 03/19/2003
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to cond	uitable title to those rights in the subjuct operations thereon.	Office Farming		
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crim statements or representations as to ar	e for any person knowingly an ny matter within its jurisdiction	d willfully to make to any department on.	or agency of the United

## COMPLETION SUBSEQUENT REPORT Gallegos Canyon Unit Com H 180E DK & Gallup 2/10/03

1/24/03 MIRU SU CHECK PRESSURE, RU7 3" FLO-LINE, BH PRESS = 310#; SICP=310#; SITP=710#. BLED OFF PRESS. KILL WELL. NDWH, NUBOP'S

1/27/03 KILL WELL w/75 BBLS 2% KCL H2O. N/D BOPs N/U BOPs. COULD NOT RELEASE SHORT STRING FROM TBG ANCHOR. SI. SDFN.

1/28/03 BLW WELL DN. RU SWIVEL & UNLOAD HOLE w/AIR/MIST, RU WL SPECIALITES & LOG ID OF 2 3/8" TBG STRING TO 4888', JET CUT SHORT STRING TBG 1  $\frac{1}{2}$ ' ABOVE TBG ANCHOR J-ASSEM IN 1  $\frac{1}{4}$ " 8' PUP JT. RD WL, TOH LD TBG ON FLOT, LEFT 1  $\frac{1}{2}$ ' IN HOLE ON J-LATCH STRINGER STUCK INSIDE OF TBG ANCHOR @4888'. SDFN.

1/29/03 SICP 52#, SITP = 0. BLW WELL DN, KILL w/30 bbls 2% KCL WTR, ND BOPS, UNSEAT LONG STRING TBG HANGER, NU BOP, HOOK-UP 2x3 LINES TO FLWBACK TANK, RU & PULL TBG, REL PKR, STING OUT OF MODEL "D" PKR SA 5562'. TOH LD LONG STRING TBG & ALL PARALLEL STRING TBG ANCHOR w/STINGER & CUT-OFF JT SHORT STRING TBG LEFT IN ANCHOR,  $5\frac{1}{2}$ " ADL-1 PKR, ALL BLAST JTS, TBG SEAL ASSEM, & SEATING NIPPLE, ALL LONG STRING RECOVERED. SDFN.

1/30/03 KILL WELL, RU PKR PLUCKER FISHING TOOL. CHG OUT TRAILERS w/TBG WK STRING. STING INTO MODEL "D" PKR @ 5562', STING OUT OF PKR. SDFN.

1/31/03 RU PWR SWIVEL, STING INTO PKR SET @ 5562' IN 5 ½" CSG w/BAKER FISHING TOOLS PKR PLUCKER, CIRC w/AIR/MIST. CUT-OVER PKR w/PKR PLUCKER, CIRC CLEAN, L/D PWR SWIVEL. TOH w/TBG. LD DCs, JARS, X-OVER BAKER PKR PLUCKER w/MODEL "D" PACKER. TIH w/ 2 3/8" TBG TO 1800'. SDF WEEKEND.

**2/3/03** TIH w/TBG TO 5600'. PU PKR & SET IN 5  $\frac{1}{2}$ " CSG @60', REL TBG FROM PKR & L/A 2 JTS TBG, LOAD HOLE w/H2O. RD RIG FLR & TONGS, ND BOPs & REMOVE OLD RECTOR WH w/2" LINEPIPE THREADS. WELD ON STUB ON 5  $\frac{1}{2}$ " x 17# CSG, NU NEW FMC WH w/FLANGED OUTLETS, PRESS TEST "P" SEALS & CSG & OK, NU BOPs, RU FLOOR & TBG TONGS, PU TBG, SCREW INTO PKR SET @ 600'. EQUALIZE PRESS, RELEASE PKR. TIH P/U TBG & TAG FILL @5900'. CIRC w/AIR/MIST, C.O FILL TO 5910'. PULL BIT ABOVE DK PERFS. SDFN.

2/4/03 SICP 480#, SITP=0, TIH w/TBG & TAG FILL @5905'. CAN'T BREAK CIRC, PRESS UP TO 1900#. TOH w/TBG. TO 4000'. BREAK CIRC & UN-LOAD w/AIR/MIST, TIH w/BIT & TBG. TAG FILL @ 5905'. C/O TO PBTD @5935'. C/O PULL BIT ABOVE DK PERFs. SDFN

2/5/03 BLW WELL DN, RIH w/TBG & BIT, TAG FILL @5927'. C/O TO PBTD. L/D PWR SWIVEL, TOHLD 2 3/8" TBG. SECURE WELL. DRAIN PMP & LINES. SDFN.

2/6/03 TIH & LAND TBG @5843'. ND BOPS & NU WH. SI RD. DRAIN LINES & PMP. SECURE WELL. RD UNIT SDFN.