30-045-10131

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211



May 27, 2004

New Mexico Oil Conservation Division Aztec District

1000 Rio Brazos Road Aztec, NM 87410 Invoice 3324

Jun 2004 Inecentad Oal Comes, div Daet, 2

1 of 2

Rig #9

For the plug and abandonment of the **HSGU #15**, a Gallup well located in NW, Section 30, T-31-N, R-16-W, San Juan County, NM. Review report for work details. This work done under NMOCD PA: 41-521-07-00028; Purchase Doc.: 04-199-000613.

Cost Summary:

Cost S	Summary:						
ID#	Date	Item Description	Units	U	nit Cost	E	xtension
Work	over Rig,	Travel and Supervision:			L		
A1	5/24/04	Contractors Supervisor / Cementer	0.5	\$	250.00	\$	125.00
A1		Contractors Supervisor / Cementer	0.5	\$	250.00	\$	125.00
A1	5/26/04	Contractors Supervisor / Cementer	1.0	\$	250.00	\$	250.00
A2	5/24/04	Crew travel, one way	1.0	\$	112.00	\$	112.00
A2	5/25/04	Crew travel, round trip time	2.0	\$	112.00	\$	224.00
A2	5/26/04	Crew travel, one way	1.0	\$	112.00	\$	112.00
АЗ	5/24/04	Shallow Rig	3.00	\$	140.00	\$	420.00
А3	5/25/04	Shallow Rig	6.25	\$	140.00	\$	875.00
А3	5/26/04	Shallow Rig	8.25	\$	140.00	\$	1,155.00
Ceme	enting Se	rvices:					
B1	5/24/04	Cementing equipment on location	0.5	\$	450.00	\$	225.00
B1	5/25/04	Cementing equipment on location	0.5	\$	450.00	\$	225.00
B1	5/26/04	Cementing equipment on location	1.0	\$	450.00	\$	450.00
В3	5/26/04	Cement, 95 sxs Type III = 106.3 sxs Type II	106.3	\$	10.50	\$	1,116.15
В3	5/26/04	Cement, set marker, 10 -III = 11.2 sxs Type III	11.2	\$	10.50	\$	117.60
Wire	line Servi	ces:	•				
C1	5/26/04	Wireline unit on location, used	1.0	\$	250.00	\$	250.00
C3	5/26/04	Perforate squeeze holes at 150'	1.0	\$	300.00	\$	300.00
Pack	ers, Retai	iners & Casing Scrapers:					
D3	5/25/04	Cement retainer, tubing set, 5-1/2"	1.0	\$	900.00	\$	900.00
D4	5/25/04	Casing scraper rental, 5-1/2"	1.0	\$	250.00	\$	250.00
Work	strings &	Miscellaneous Rentals:		,			
E1.1	5/25/04	Workstring rental, 2-3/8, feet	1081	\$	0.12	\$	129.72
E6.3	5/25/04		1.0	\$	50.00	\$	50.00
E7.1	5/25/04		1.0	\$	100.00	\$	100.00
E14	5/26/04	Waste fluid container, days used	2.5	\$	30.00	\$	75.00

A-PLUS WELL SERVICE, INC.



P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

May 27, 2004

New Mexico Oil Conservation Division

2 of 2

Aztec District

1000 Rio Brazos Road

Invoice 3324

Rig #9

Aztec, NM 87410

For the plug and abandonment of the **HSGU #15**, a Gallup well located in NW, Section 30, T-31-N, R-16-W, San Juan County, NM. Review report for work details. This work done under NMOCD PA: 41-521-07-00028; Purchase Doc.: 04-199-000613.

Cost Summary:

Continued:

ID#	Date	Item Description	Units	U	nit Cost	E	xtension
Tran	sportatio	n and Miscellaneous Services		- N. J.		-	
F1.a	5/24/04	Unit #141, Haul waste pit # 525 and workstring	1.0	\$	74.00	\$	74.00
F1.b	5/25/04	Unit #141, Move workstring into position	2.0	\$	74.00	\$	148.00
F1.c	5/26/04	Unit #141, Hold workstring on float	1.0	\$	74.00	\$	74.00
F1.d	6/1/04	Unit #24, Haul tubing to Cave Ent.	1.25	\$	50.00	\$	62.50
F2.d	6/1/04	Helper for above	1.25	\$	20.00	\$	25.00
F1.e	6/3/04	Unit #152, Haul waste pit to IES landfarm, dump;	1.25	\$	74.00	\$	92.50
F2.e	6/3/04	Helper for above	1.25	\$	20.00	\$	25.00
F4	5/26/04	Float with workstring, rental	2.0	\$	15.00	\$	30.00
F6.a	5/21/04	Unit #265, Haul 1 load of water to central tank	4.5	\$	50.00	\$	225.00
F14	5/21/04	Purchase water , above	1.0	\$	20.00	\$	20.00
F6.b	5/24/04	Unit #134, Haul 1 load of water to location	1.0	\$	50.00	\$	50.00
F6.c	5/25/04	Unit #134, Hold fresh water on location	2.0	\$	50.00	\$	100.00
F6.d	5/26/04	Unit #134, Haul 1 load of water to location	2.0	\$	50.00	\$	100.00
F6.e	5/24/04	Unit #155, Haul / hold waste water from steel pit	1.0	\$	50.00	\$	50.00
F6.f	5/25/04	Unit #155, Haul / hold waste water from steel pit	2.0	\$	50.00	\$	100.00
F6.g	5/26/04	Unit #155, Haul / hold waste water from steel pit	1.0	\$	50.00	\$	50.00
F7	5/19/04	B-hoe, Clean up location and wellhead	3.0	\$	- 50.00	\$	150.00
F2	5/19/04	Helper for B-hoe, pick up trash and load junk	3.0	\$	20.00	\$	60.00
F11	4/26/04	P&A marker, purchase	1.0	\$	120.00	\$	120.00
Third	i Party Se	rvices:					
G1	6/3/04	Industrial Ecosystems, Inv #4073, land farm	1.0	\$	80.00		
			Total	\$	80.00		
		Third Party Handling Charge	8%	\$	6.40	\$	86.40
Salva	age Credi	t:					
S1	•	2-3/8" EUE tubing, 35 joints, paraffin inside	1085	\$	0.70	\$	(759.50)
		n. um	ber	TO	TAL.	\$	8,344.37
		L. V. RAI.	TAX ر ا	6	.3750%	\$	531.95
THAN	K YOU	t: 2-3/8" EUE tubing, 35 joints, paraffin inside	4	TO	TAL DUE	\$	8,876.32

Charles 10-04

BEPUTY OIL & GAS INSPECTOR, DIST.

ORIGINAL SIGNED BY CHARLIE T. PERRIM

submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports on Wells

			5.	Lease Number BIA #14-20-603-734
Toma of Mall			6.	If Indian, All. or
. Type of Well			0.	Tribe Name
WIW				
				Navajo
			7.	Unit Agreement Name
. Name of Operator				Horseshoe Gallup Unit
Vulcan Minerals Energy	C/o NMOCD		_	
			8.	Weil Name & Number
Address & Phone No. of C				HSGU #15
1000 Rio Brazos Road, Az	ztec, NM 87410 505-334-6178	3	9.	API Well No.
				30-045-10131
ocation of Well, Footage, Se	c., T, R, M		10.	
				Horseshoe Gallup Unit
1980' FSL and 660' FWL,	Section 32, T-31-N, R-16-W,		11.	County & Stat
				San Juan County, NM
2. CHECK APPROPRIATE B	OX TO INDICATE NATURE C	F NOTICE, REPORT, OT	HER D	DATA
Type of Submission	Type of Action			
Notice of Intent	X Abandonment	Change of Plans		
	Recompletion	New Construction		
X Subsequent Rep	•	Non-Routine Fracti	ırina	
	Casing Repair	Water Shut off	3	
Final Abandonme		Conversion to Inject	tion	
Tillar / Ibandonin	Other -			
	Plugged and Abandoned th t Number: 04-521-0700028			
3/25/04 No pressure on well. packer. Tally and Pt	line to steel pit. Blow down we Change out tubing head. NU J 34 joints A+ workstring and DHS cement retainer not set.	J BOP, test. TOH and LE I round-trip 5-1/2" casing	35 joi scrape	nts 2-3/8" tubing and r to 1081'. TIH with
/26/04 Set 5-1/2" DHS ceme with 26 bbls of water. fluid below retainer, d cement inside casing	ent retainer at 1081'. Sting o Pressure test casing to 500# isplace to CR. Sting out of re above CR up to 696' to isolat	ut of retainer. Load casing for 5 minutes, held OK. Stainer. Plug #1 with CR are the Gallup interval. TO	ng and Sting in t 1081', H and	establish circulation to retainer and pump , spot 40 sxs Type III LD tubing. Perforate
bbls of water to circu casing from 150' to	50'. Establish circulation out bulate BH annulus clean. Plug surface, circulate good ceme ment down 12' in 5-1/2" cas marker.	g #2 with 45 sxs Type III ant out bradenhead. ND	cemer BOP.	nt pump down 5-1/2" Dig out and cut off
	D, L. Lee and W. Ashley, NNN	/ID, J. Walker, EPA were o	on loca	tion.
SIGNATURE <u>Mallu</u> William F. Clark	it the cont	ractor	M	lay 31, 2004
his space for Federal or State	Office use)			
PPPOVED BY	Title			Date

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

#9 Date 05/24/04 Rig No_ Day Mon PLYA MINERALS & ENERGY

Vell Nam	e HOKSES	HOE GALLUP UNIT 15 Company PUYA MINERALS & ENERGY
FROM	то	DESCRIPTION OF OPERATION
1:30	2:30	ROAD RIG AND EQUIPMENT TO LOCATION
2:30	3:30	SPOT RIL. RIL UP.
3:30	4:00	MIPPLE UP FLOWLINES TO PIT. BLED WELL DOWN.
4:00		NIPPLE DOWN WELL HEAD
		RELEASE PACKER. NEED 5/2"NIPPLE TO CHANGE OUT WELLHEAD.
	4:30	SECURE WELL
4:30	5:30	TRAVEL TO YARD.
	ļ	
	-	
	 	
	 	
· · · · · · · · · · · · · · · · · · ·		- Carry Carry
	 	
	<u> </u>	
		
	1	:
	-	

Fuel & Motor Oil	Water Hauled
Rental Equipment	Cement Retainers
Cementing	
Wireline	

1/2 day

CREW	NAME:	UNIT #	MILEAGE	HOURS
Supervisor	MIKE HIGDON	421		
Operator	ADAN REYES	±13		4.0
Helper	LORENZO RUPRIGUEZ			4.0
Helper	CHRIS MONTANEZ			4.0
Helper	24.000			
Trainee				

RCI Form - 0801114A

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

22421

•	Rig No_	*9		Date <u>05/25/</u>	04 Day T	u£
	Well Nam	e Horse	SHOE GALLUP UNIT # 15	Company PLAY	A MINERALS	LENERUY
	FROM	то	DESCRIPTIO	N OF OPERATION		
	6:00	6:15	LOAD RIL SUPPLIES			
17	6:15	7:15	TRAVEL TO LOCATION			
1 h	7:15	7:45	START RIG AND EQUIPMENT HELD	PRE-JUB SAFETY ME	ETING.	
	7:45		OPEN WELL (NO PRESSURE)			
			NIPPLE DOWN WELLHEAD.			
. , ;		10:15	NIPPLE UP BOP/COMPANION FLANC		TEST RAMS,	
11/1 M	10:15	11:00	LAY DOWN THE AND PACKER.	(35 STS -23/8")		
61/4 hu	11200	ļ	PICK UP AND TH / 51/2"CSG:	SCRAPER AND 34 JTS	- 2 1/8 A-PLU	SWORK
		11:45	STRING , EOT @ 1081.			
<i> </i>	11:45	12:30	TOH/ TBG AND SCRAPER.			
	12:30		TIH/51/2" DHS CRT AND TOG.	LEFT CRT UNSET. (WA	TER PUMPOUT	ON PUMP TRUCK
		1:30	SECURE WELL.			
	1:30	2:30	TRAVEL TO YARD.	<u> </u>	<u> </u>	
1.7	-	<u> </u>	· · · · · · · · · · · · · · · · · · ·			
1 M						
1						****
2						
		†				
						1
				 		
		<u> </u>				
•		 	LERCY LEE NAUNSO EPA			
		<u></u>	HENRY VILLANGED / NMOCD			
	Fuel & M	lotor Oil _	Wate	r Hauled		
	Rental E	quipment	Cem	ent Retainers 51/2 OHs @	1081	
: !	Wireline					
11/	CRE	€W	NAME	UNIT #	MILEAGE	HOURS
lidas	Super	visor	MIKE HICPON	#21		
	Opera	tor	ADAN REYES	[#] 19		8.5
	Helpe	r	LORENZO RUDRIGUEZ			8.5
:T	Heipe	r	CHRIS MONTANEZ			8.5
	Helpe	r	GURDON HACKETT			8.5

Trainee

GURDON

HACKETT

FROM

P.Ö. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

DESCRIPTION OF OPERATION

	¥	9		
Ria No		/		

Date 05/26/04 Day WED

Well Name HORSESHOE GALLUP UNIT # 15

Company PLAYA MINERALS & ENERGY

ImT

5:30 5:45 LOAD RIL SUPPLIES 5:45 6:45 TRAVEL TO LOCATION 6:45 7:15 START RIG AND EQUIPMENT, HELD PRE-JOB SAFETY MEETING. 7:15 OPEN WELL (NO PRESSURE) SET CIET @ LOBI STING OUT OF CET, PUMP 26 BBLS WATER TO CIRCULATE HOLE CLEAN. PRESSURE TEST CSC TO 500 PSI. HELD PRESSURE 8:00 5 MIN. NO PRESSURE LOSS: BLED PRESSURE OFF. 8:00 STING INTO CRT, INSECT FLUID FROM PIT BELOW CRT. DISPLACE / FRESH 9:00 WATER. STING OUT OF CRT. PLUGAL - MIX AND PUMP 40 SXS TYPE II 14.7° CMT FROM 1081 TO 9:30 TOCA 696' DISPLACE. 10:15 LAY DUWN TBG AND STINGER. RIGUP WIRELINE RIH/WIRELINE, PERFORATE 2-21/8 SQUEEZE HOLES @ 150. POH WIRELINE. RIL DOWN WIRELINE. PUMP 2 1/2 BBLS WATER DOWN CSG TO CIRCULATE OUT BRADENHEAD 10:45 11:00 CIRCULATE CLEAN AN ADDITIONAL 12 BBLS. 11:00 PLUG #2 - MIX AND PUMP 455x5 TYPE III 14.8 CMT DOWN CSG TO CIRCULATE GOOD CAT OUT BRADENHEAD. 11:30 11:30 12:30 NIPPLE DOWN BUT/COMPANION AND TRU HEAD. 12:30 DIG OUT AND CUT OFF WELLHEAD. CMT @ 12' IN 51/2"CSG 2:00 PLACE PLA MARKER /10 SXS CMT @SURF IN 85/8 CSC 2:00 3:00 RIL DOWN, CUT OFF RIL ANCHORS.

INT

Rental Equipment Cement Retainers

Cementing PLUC 4/- 40 Sxs TYPE II PLUC 2-45 Sxs TYPE III PLU Sxs

Wireline 2-2/8 8/- WIRE SHOTS @ 150 (NI. H.)

WALLACE ASHLEY NAVAJO MINERALS

JIM WALKER / US EPA

HENRY VILLANUEVA NMOCO

LEROY LEE/NAVAJO EPA

1 day

CREW	NAME	UNIT#	MILEAGE	HOURS
Supervisor.	MIKE HIGDON	#21		
Operator ·	ADAN REYES	#19		9.5
Helper	LORENZO RODRIGUEZ			9.5
Helper	CHRIS MONTANEZ			9.5
Helper	GORDON HACKETT			9.5
Trainee	A CANADA		•	

FICI Form - 0801114

A-Plus Well Service, Inc. P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date:	Truck #: _	/11	
Event: #1	From: H6u #27 To: H6u #15	Hours	
Start:	What: HAUL WORKSTRWG (FLUAT #98) AND STEEL PIT \$515		117
05/24/04	TO LOCATION.		Fl. 7
Stop:	Charge to: PLAYA MINERALS & ENERGY YO NMOCD	1.0	, ,
Event: #2 Start:	From: HGU # 15 To: What: STANDBY FOR RIG UP TRUCK.		
05/25/04	What: STANDBY FOR RIC UP TRUCK,		1
Stop:	Charge to: PLAYA MINERALS & ENERGY YOUNDOLD	2.0	12
Totop:		_l d .∙⊘	Y1'
Event: #3	From: 116 U 15 To:		
Start:	What: STANDBY FOR RIC UP TRUCK		^
05/26/04			
Stop:	Charge to: PLAYA MINERALS & ENERGY YO NMOCO	11.0	Fl.b Fl.C
Event: #4	From: To:		
Start:	What:		
a se f	and the second of the second o		
Stop:	Charge to:		
Event: #5	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #6	From: To:		•
Start:	What:		
Stop:	Charge to:		
Event: #7	From: To:		
Start:	What:		
Otal I.			• •
Stop:	Charge to:		
Event: #8	From: To:		
Start:	What:		
Otari.	The state of the s		
Stop:	Charge to:		
	Driver: MIKE HIGDON	4 .0	
Diesel:	Helper	7.0	
Oil:	NM MILES: CO MILES: UT MILES:	<u> </u>	1
	OT MILES.		
Remarks:			
			•
		4 42	
		21. 1. 10.	
1			
	1		

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date: 6 / 04 Truck #: クソ To: CAVE Event: #1 From: 4-PW Hours What: Por TOID UNIT BY STATE Charge to: Stop: 2.60 CAUE PIPE Event: #2 To: What: Long 1/21 87 0078 .25 Start: イ ' o ら Duit 24 STATE :75 Charge to: Stop: 🟑 To: CANE Event: #3 From: A-P-W 25 What: DRIVE Start: ///S 10 CANE 2.5hu 1/2 to 15 Stop: 6, 30 STATE Charge to: To: Event: #4 From: /ZUC Start: 6 / 3つ What: MULDADED Stop: 7/36 Charge to: STATE Event: #5 From: CAUC To: ل سر بهر سرم 5 Start: 7/33 What: ORIUS Stop: Pi'60 Charge to: 57200 From: D-P-W To: Event: #6 What: PROTRIP Start: 8100 60 8815 420 £ 2010 Charge to: Stop: STATE From: A-P-LU To: کاکنے Event: #7 STORAGE TANK Start: 9/15 What: ORIVE TO HISE LUZDAG WATTER BRIDE BACK J. Stop: /2, 00 Charge to: 5-11-12 Event: #8 From: To: Start: What: Stop: Charge to: Driver: NOMUE (TOSTIN Diesel: 42. 0 Helper TASON BIZZCEC NM MILES: 53 HWY CO MILES: UT MILES: कुठ गाउँ Remarks: 456-11 #15 A MOCA TASON JUST ChiCADED PIPE

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date: 6 304 Truck #: 152 From: HINTLAND To: A-PW Event: #1 Hours Start: /30 What: Drive To VARD Charge to: Stop: 2,00 Event: #2 From: A-P-W To: Start: 2:00 What: OROP JUNK BASKET & LOAD 535 Stop: ノバく Charge to: From: A-P-W Event: #3 To: KSGU 128 Start: 2:13 What: Stop: 3,45 Charge to: 3 3/4 hu Event: #4 From: 436 128 To: Start: *3,1*43 What: DROP 525 CLOAD 5/3 Stop: ೭/ での Charge to: Event: #5 From: 1/5/5 To: 5 Start: 4100 What: ORIUS IFI Stop: 5, 30 Charge to: IEI Event: #6 From: To: Start: 5.30 What: 515 EMPTY Stop: 5, 45 Charge to: To: A-P-W From: エィエ Event: #7 What: ORIUS 10 25 (hab Stop: ゟ,゚ゟゟ Charge to: Event: #8 From: To: Start: What: Stop: Charge to: DUNNE (QUSTIN 4.5 Driver: / Helper Diesel: 7136~ BITTELL NM MILES: 158 Oil: CO MILES: UT MILES: Remarks: 100 HWY-Y2018T

A-Plus Well Service, Inc.P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: <u>5 - 9</u>	1-04 Truck #:	268	-
Event: #1	From: A - plus To:	Hours	
Start: 5:30	What: Pre CK 265		
Stop: 6,00	Charge to: $\mathcal{N} \mathcal{A}, \mathcal{O} \subset \mathcal{O}$	15	
stop: 6,00	Charge to: NM. OCP		
Event: #2	From: Farmint hydraut To: Horsestoe Cally		
Start: / '.00	What: hauld I load From Farmyton		9 hrs
<u> </u>	haulal I load from Ship rock	7	
Stop: /00	Charge to: W_FL. O.C.D		
Event: #3	From: Horsechar Collys To: 17-plu		
Start: /:00	What: Roal This is		
		1.5	Ą
Stop: 1.30	Charge to: NA OCD		
Event: #4	From: To:		
Start:	. What:		
and the second second	and the second of the second o		
Stop:	Charge to:		
Event: #5	From: To:		1
Start:	What:		Fl.
			"
Stop:	Charge to:		
Event: #6	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #7	From: To:		
Start:	What:		
C4	Character in the control of the cont		
Stop:	Charge to:		
Event: #8	From: To:		
Start:	What:		
Stop:	Charge to:		
otop.	Total de to:		
	Driver: Lely Mag	. G	
Diesel:	Helper 56 out		
Oil:	NM MILES: 48 CO MILES: UT MILES:		
			
Remarks:	Alma: 0		
·	WINDLD MSGN 15		1,1
	11.1		7 /
	Hall & londs My to	`	ľ
	Central tone buttery		4
<u> </u>		10	Pos
	Load	4-66	150

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date:	Truck #: _	134	-
Event: #1	From: HGU #27 To: HGU #15	Hours	/
Start:	What: HAUL I LOAD FRESH WATER TO LOCATION		6/2
05/24/09			<i>P</i> 0.0
Stop:	Charge to: PLAYA MINERALS & ENERGY % MOCD	1.0	F6.6 F6.C
Event: #2	From: #HGu #15 To:		~/ (<u>'</u> .
Start: 0 5/25/04	What: STANDBY FOR FRESH WATER		16.0
5 5 /2 5 / 0 4 Stop:	Charge to: PLAYA MINERALS SENERLY % NAUCD	2.0	'
		197.	/
Event: #3	From: HGu [#] 15 To:		110
Start:	What: HAUL I LOAD FRESH WATER		1-6
05/26/04			
Stop:	Charge to: PLAYA MINERALS & ENERGY % NMOCD	12.0	
Event: #4	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #5	From: To:		
Start:	What:		
			-
Stop:	Charge to:		
Event: #6	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #7	From: To:		
Start:	What:		·
			• •
Stop:	Charge to:		
Event: #8	From: To:		
Start:	What:		
Stop:	Charge to:		
[6	
	Driver: MIKE HIGDOW	7.0	
Diesel:	Helper		
Oil:	NM MILES: UT MILES:].
Remarks:			
·			
			. ·
			† :
L			L

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date:	Truck#: <u>15</u>	<u> </u>
Event: #1	From: HGu #29 To: HGu #15	Hours
Start:	What: RUAD TO LOCATION STANDBY FUR DISPOSAL	
05/24/04	,	
Stop:	Charge to: PLAYA MINERALS & ENERGY % NMOCO	1.0
	I #	
Event: #2	From: HGU 215 To:	
Start:	What: STANOBY FOR DISPOSAL	
05/25/04 Stop:	Charge to: PLAYA MINERALS & ENERCY YO NMOCH	2.0
Event: #3	From: HGu #15 To:	
Start:	What: STANDBY FOR DISPOSAL	
05/26/04		
Stop:	Charge to: PLAYA MINERALS & ENERCY YO MOCID	1.0
Event: #4	From: To:	
Start:	What:	
Management of the second second second	Appendix App	
Stop:	Charge to:	
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
F	Т	,
Event: #7 Start:	From: To: What:	
Start.	Wildt.	<u> </u>
Stop:	Charge to:	<u>:</u>
		1
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
		·
	Driver: MIKE HIGDON	1.0
Diesel:	Helper	ن دور
Oil:	NM MILES: CO MILES: UT MILES:	
B		
Remarks:		
Ar	the state of the s	
		

F6.9

A-Plus Well Service, Inc. P.O. Box 1979, Farmington, NM 87499 505-325-2627

NO CMV

Date: <u> </u>		ruck #: <u>34</u>
Event: #1		Hours
Start: 5. 30	From: A-P-W To: JSGV What: PRE TRIP WMIT 34 6 85	
	<u> </u>	. 5
top:∠, 60	Charge to:	
	From: LISGU # 14 To: What: CLEAN & LOUAL LOCATION OONE	
Start: 6, '00	What: CLEAR & LOUGH LOCATION	3
	DONE	
Stop: <i>5,'60</i>	Charge to:	
vent: #3	From: ASGV # 15 To: What: CLEAN & LEVEL LOCATION	3 3 1
Start: 9,100	What: CLOAN & LOVEL LOCATION	3 7
	DONE	JAN SAN
Stop: /2,60	Charge to:	1
vent: #4	From: 4/56/0 18/28 To:	
Start: /3/00	From: HSGO #12B To: What: CLEAN & LEVEL LOCATION	435
4:00	DONI	
Stop: 🝠 🗪	Charge to:	
vent: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	///
Ston	Charge to:	
Stop:	Charge to:	
	Deliver	10,5
Diagoli /477	Driver: DUNNE (JUSTA)	
Diesel: <u>/57.7</u> Dil:	NM MILES: CO MILES: UT MILES:	10.5
/II.	NM MILES: CO MILES: UT MILES:	
Remarks:	6.0 GANGONS IN TRK	
-	9.7 Gareens Brek Hot	
	MOCD HEGY = 15	
		Shun
	I flow o finish day the land	
	Han a level location	RCI Form - ORDISAA

ATTN: BILL

325-1211

Invoice Number: 4073

Invoice Date:

Jun 7, 2004

Page:

Industrial Ecosystems Inc.

estems Inc.

P.O. Box 2043

Farmington, NM 87499 PH: (505) 632-1782

Fax: (505) 632-1876

TAX I.D. #94-3200034

PLEASE REMIT PAYMENT TO: Industrial Ecosystems, Inc. c/o John J. Kiely 401 S. Lasalle St., Suite 606

Sold To: A PLUS WELL SERVICE

PO BOX 1979

FARMINGTON, NM 87499

Location: DENNY FOUTZ

HORS SHORE WALL UP #128

Chicago, Illinois 60605

Contacte and Misc Jonacus Payment Terms		Due Dat	e <u> </u>	ustomer PO
DENNY FOUTZ	Net 30 Days	7/7/04		
Quantity	Description		Unit Price	Extension
	6/2/04			
•	MATERIALS TRANSPORTED BY: APLUS TRUCKING	- TRUCK#152	I	
1.00	DISPOSED OF CEMENT WASTE DISPOSAL CHARGE		210.00	210
	#15 - #14 - #128	8000		
	#14 -	65	6	-()
	#128	210		
			,	
	Mark the Committee of t	ĺ		
	en e	į		

FOR BILLING INQUIRIES PLEASE CALL (505) 632-1782

ACCOUNTS ARE DUE NET 30 DAYS. PURCHASER AGREES TO PAY FINANCE CHARGES OF 1.5% PER MONTH (ANNUAL PERCENTAGE RATE OF 18%) OR A MINIMUM CHARGE OF 50 PER MONTH. ACCOUNTS THAT HAVE BEEN PLACED FOR COLLECTION WILL BE CHARGED A \$100.00 COLLECTION FEE IN ADDITION TO REASONABLE ATTORNEY FEES AND COLLECTION CHARGES.

Subtotal Sales Tax

Total Invoice Amount

210.00

210.00

TOTAL

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

May 31, 2004

CAVE Enterprises

PO Box 79 Flora Vista, NM 87415

Invoice #3329-A

Rig #9

For used tubing from Horseshoe Gallup Unit wells, located in Section 30 and 31, T31N, R16W, San Juan County, NM.

This material was credited to NMOCD on the appropriate invoice.

Cost Summary:

HSGU Well	Feet	Type and Size	Va	alue	S	alvage
#16	1085	35 joints 2-3/8" tubing, fiberglass lined	\$	0.70	\$	759.50
#17	1085	35 joints 2-3/8" tubing, fiberglass lined	\$	0.70	\$	759.50
#27	1240	35 joints 2-3/8" tubing,	\$	0.80	\$	868.00
#29	1240	40 joints 2-3/8" tubing,	\$	0.80	\$	992.00
#14	1178	38 joints 2-3/8" tubing, heavy paraffin	\$	0.60	\$	706.80
#15	1085	35 joints 2-3/8" tubing, paraffin inside	\$	0.70	\$	759.50
#128	1023	33 joints 2-3/8" tubing, paraffin inside	\$	0.70	\$	716.10
					\$	5,561.40
		NM TAX Ex	empt - F	Resale		
THANK YOU			TOTAL	_ DUE	\$	5.561.40