Office	State of New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	, Minerals and Natural Resources	WELL API NO.
1501 11. Olalia 1110., 1210514, 1111 00210	CONSERVATION DIVISION	30-045-31875 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. E-286-39
SUNDRY NOTICES AND RI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILI		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PI PROPOSALS.)	ERMIT" (FORM C 101) FOR SUCH	Burroughs Com A
1. Type of Well:		8. Well Number
Oil Well Gas Well X Other	2000	#100S
2. Name of Operator Burlington Resources Oil & Gas Company Ll		9. OGRID Number 14538
3. Address of Operator	E COLLEGE OF	10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM 87499-4289 4. Well Location		Basin Fruitland Coal 71629
1 State of the sta		
Unit Letter O: 810 feet from the South line and 1490 feet from the East line		
Section 16 T	Cownship 32N Range 10W	NMPM San Juan County
11. Elevation	on (Show whether DR, RKB, RT, GR, etc.	:.)
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)		
Pit Location: ULSectTwpRng		· · · · · · · · · · · · · · · · · · ·
Distance from nearest surface waterBelow-gr		PRng;
feet from theline andfeet from	n theline	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND	ABANDON REMEDIAL WO	
TEMPORARILY ABANDON CHANGE F	PLANS 🗆 COMMENCE DI	RILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETI		AND
OTHER:		
O 11 12 1 11	☐ OTHER: LO	G detail
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU	ons. (Clearly state all pertinent details, a	
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods. tbg & land @ 3116' w/SN @ 3089' (new depth).	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: And Multiple C	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion H w/tubing. Change BHA, TIH w/2-3/8", 4.7#
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods.	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: And Multiple C	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion H w/tubing. Change BHA, TIH w/2-3/8", 4.7#
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods. tbg & land @ 3116' w/SN @ 3089' (new depth).	ND WH & NU & test BOP-OK. TOO RD floor. ND BOP, NU WH. TIH w/tr	Ind give pertinent dates, including estimated date attach wellbore diagram of proposed completion. H w/tubing. Change BHA, TIH w/2-3/8", 4.7# bing pump plunger, pump & rods. Spaced out. ge and belief. I further certify that any pit or below-
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods. tbg & land @ 3116' w/SN @ 3089' (new depth). PT – OK. RD & released rig @ 1000 hrs 6/9/04 I hereby certify that the information above is true	ND WH & NU & test BOP-OK. TOO RD floor. ND BOP, NU WH. TIH w/tr	Ind give pertinent dates, including estimated date attach wellbore diagram of proposed completion. H w/tubing. Change BHA, TIH w/2-3/8", 4.7# bing pump plunger, pump & rods. Spaced out. ge and belief. I further certify that any pit or below-lor an (attached) alternative OCD-approved plan .
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods. tbg & land @ 3116' w/SN @ 3089' (new depth). PT – OK. RD & released rig @ 1000 hrs 6/9/04 I hereby certify that the information above is true grade tank has been/will be constructed or closed according.	ND WH & NU & test BOP-OK. TOO RD floor. ND BOP, NU WH. TIH w/to and complete to the best of my knowledg to NMOCD guidelines , a general permit	Ind give pertinent dates, including estimated date attach wellbore diagram of proposed completion. He w/tubing. Change BHA, TIH w/2-3/8", 4.7# bing pump plunger, pump & rods. Spaced out. In ge and belief. I further certify that any pit or below- I or an (attached) alternative OCD-approved plan . He is a significant of the complete of the complete of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certify that any pit or below- He is a significant of the certificant of
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods. tbg & land @ 3116' w/SN @ 3089' (new depth). PT – OK. RD & released rig @ 1000 hrs 6/9/04 I hereby certify that the information above is true grade tank has been/will be constructed or closed according SIGNATURE Type or print name Patsy Clugston	ND WH & NU & test BOP-OK. TOO RD floor. ND BOP, NU WH. TIH w/to and complete to the best of my knowled to NMOCD guidelines, a general permit [Ind give pertinent dates, including estimated date attach wellbore diagram of proposed completion. He w/tubing. Change BHA, TIH w/2-3/8", 4.7# bing pump plunger, pump & rods. Spaced out. ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan . ialist DATE 6/30/04
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. PLUNGER/PUMP REPAIR 6/8/04 MIRU TJR #5. COOH w/plunger & rods. tbg & land @ 3116' w/SN @ 3089' (new depth). PT – OK. RD & released rig @ 1000 hrs 6/9/04 I hereby certify that the information above is true grade tank has been/will be constructed or closed according. SIGNATURE	ND WH & NU & test BOP-OK. TOO RD floor. ND BOP, NU WH. TIH w/to and complete to the best of my knowled to NMOCD guidelines, a general permit [Ind give pertinent dates, including estimated date attach wellbore diagram of proposed completion. He w/tubing. Change BHA, TIH w/2-3/8", 4.7# bing pump plunger, pump & rods. Spaced out. ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan . ialist DATE 6/30/04